

AGS. REC'D BY: T. J. M.

REF: CS/F.C.I. 27012044/743

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 938K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 9BE1770D Yr Regn: 2015, Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Pick-up

Make: Ssangyong Actyon D/Cab C.C 1998

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 236608 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPA1741ETSE P238977

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size: F: 225/75R16

R: u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 5/12/22

Survey held at Twin wheels

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS. \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B. / P. _____

TWIN WHEELS AUTO TRADING ENTERPRISE

38 Woodlands Industrial Park E1 #03-14

Singapore 757700

TEL: 6457 0410 / 6765 2616

EMAIL: twinauto@singnet.com.sg

3 December 2022

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: ALPHA FUMIGATION SERVICES PTE LTD

H/P: 9856 2733

Dear Sirs / Madam,

**Accident Claim for Vehicle No.GBE 1770 D, Involving Vehicle No.GBF 42 Z.
Accident on 30 NOVEMBER 2022, AT CHOA CHU KANG AVE 4 (BETWEEN
OF BLK 458 & 470).**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	HEADLAMP RH ✓	1PC	
2	HEADLAMP RETAINER ?	1PC	
3	FRONT BONNET RV	1PC	
4	FRONT BONNET HINGES X	2PCS	
5	HEADLAMP RUBBER ?	1PC	
6	FRONT GRILLE X	1PC	
7	FRONT BUMPER de ✓	1PC	
8	FRONT BUMPER RETAINER RH de - LH X	2PCS	
9	FRONT BUMPER SPORT LAMP, crn ✓	1PC	
10	FRONT BUMPER SPORT LAMP BRACKET crn ✓	1PC	
11	FRONT SUPPORT PANEL X	1PC	
12	FRONT FENDER - RH h ✓	1PC	
13	FRONT FENDER COWLING - RH de ✓	1PC	
14	FRONT FENDER LAMP - RH sig ✓	1PC	
15	FRONT FENDER TOP RUBBER - RH ?	1PC	
16	FRONT WHEEL BEARING - RH X ?	1PC	
17	FRONT WHEEL BEARING HUP - RH X ?	1PC	
18	FRONT UPPER ARM - RH X	1PC	
19	FRONT LOWER ARM - RH X	1PC	
20	FRONT KNUCKLE - RH X	1PC	
21	FRONT SHOCK ABSORBER - RH X	1PC	
	TOTAL LIST PRICE		
	LESS 10%		
	TOTAL AMOUNT		

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	FRONT BONNET STICKER	1SET	\$ 100 180.00
2	FRONT SPORT RIM - RH	1PC	\$ X 480.00
	TOTAL SPECIAL NETT PRICE		\$ 660.00

	LABOUR :		
1	LABOUR TO SPRAY PAINT		\$ 700 1,000.00
2	LABOUR TO PANEL BEATING		\$ 600 900.00
3	LABOUR TO DISMANTLE AND REFIX REAR UNDER CARRIAGE.		\$ X 150? 250.00
4	COMPUTERISED WHEEL ALIGNMENT		\$ 3 80 120.00
5	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS		\$ 30 100.00
6	LABOUR TO FOCUS HEADLAMP		\$ 30 40.00
7	LABOUR TO DISMANTLE AND REFIX AIRCON COOLING SYSTEM PARTS. VACUUM AND RE-CHARGE AIRCON GAS-R134.		\$ X 180.00
	TOTAL LABOUR	\$	2,590.00
	TOTAL AMOUNT		

THANK YOU

FROM:

Twin Wheels Auto Trading Enterprise

Mr Tan Leng Huat

Tan Jiah 9749 5749 / 62563561
 WP 5/17/22 @ 3:45pm
 Tan Jiah @ kh auto. w n
 4 days
 L/S Resurvey after repair
 Tan Jiah @ kh auto. w n

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____