

Chew Goon Motor (Co.Reg.No:22188000C)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Tel: 64841626 Fax: 64840465 Email: aaronm3@chewgoonmotor.com.sg;chewgoon@singnet.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SKT8618E
Policy No:	SP2002011877-01	Date of Loss:	21/11/2022
Vehicle Reg. No.:	SKT8618E	Driveable?	
Driver Age/Info:	31	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEN DESHENG	Contact No:	+6588686681
Driver:	CHEN DESHENG		
Make/Model:	MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A)	Vehicle Reg. Date:	25/06/2015
Vehicle Colour:	Blue		
Engine No:	27091030665978	Chassis No:	WDD1173422N216610
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 10

Description of Accident/Loss REFER TO SKETCH PLAN.

Present Location: CHEW GOON MOTOR (AMK)

COST OF CLAIMS

	Amount
Parts	10,845.90
Miscellaneous Items	0.00
Labour	2,180.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	13,025.90

This claim is handled by: KUEK SUE FANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Dec 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Chew Goon Motor/SKT8618E/01/12/2022 15:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Grille	0.00	0.00	*350.00 F
2	1		*Grille Emblem	0.00	0.00	*75.00 F
3	1		*Grille Emblem Base Bracket	0.00	0.00	*38.00 F
4	1		*Front Bumper	0.00	0.00	*650.00 F
5	10		*Front Bumper Clips	0.00	0.00	*40.00 F
6	2		*Front Bumper Brackets	0.00	0.00	*250.00 F
7	1		*Front Bumper Sponge	0.00	0.00	*100.00 F
8	1		*Front Bumper Reinforcement	0.00	0.00	*225.00 F
9	1		*Front Bumper Center Air Grille	0.00	0.00	*76.00 F
10	1		*Front Bumper Sensor	0.00	0.00	*135.00 F
11	4		*Front Bumper Sensor Holders	0.00	0.00	*100.00 F
12	1		*Front Bumper Top Core	0.00	0.00	*150.00 F
13	1		*Front Bumper Top Beam	0.00	0.00	*220.00 F
14	2		*Front Bumper Inner Side Cores	0.00	0.00	*90.00 F
15	2		*Front Bumper Top Retainers	0.00	0.00	*50.00 F
16	1		*Front Bumper Inner Collision Preventive Sensor	0.00	0.00	*135.00 F
17	1		*Front Bumper Inner Collision Preventive Sensor Module	0.00	0.00	*1,320.00 F
18	1		*Front Bumper Emblem	0.00	0.00	*30.00 F
19	1		*Front Bumper Top Rubber Seal	0.00	0.00	*30.00 F
20	1		*Front Bumper Number Plate Holder	0.00	0.00	*80.00 F
21	2		*Headlamps	0.00	0.00	*2,900.00 F
22	1		*Support Panel	0.00	0.00	*275.00 F
23	1		*Air Con Condenser	0.00	0.00	*540.00 F
24	1		*Air Con Condenser Side Air Guide	0.00	0.00	*120.00 F
25	1		*Turbo Inter-Cooler	0.00	0.00	*450.00 F
26	1		*Radiator	0.00	0.00	*590.00 F
27	1		*Bonnet	0.00	0.00	*800.00 F
28	1		*Front Number Plate	0	0.00	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **9,864.00**
+ Margin on L,N Items 10.00% (\$\$) **981.90**

Total Parts (\$\$) **10,845.90**

Chew Goon Motor/SKT8618E/01/12/2022 15:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To Conduct Electrical Check, Focus Headlamp	New	30.00
2	To Remove / Refit Air Con Condenser & Refill Air Con Gas	New	100.00
3	To Remove / Refit, Radiator System, Bleed, Refill Coolant	New	50.00
4	Labour Charge - Panel Beating, Repairing of Front Chassis, Inner Panel, Front Fender & Part Replacement	New	600.00
5	To Respray Affected Areas	New	1,400.00
Gross Labour Cost (\$\$)			2,180.00

Chew Goon Motor/SKT8618E/01/12/2022 15:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >