

Taufik

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Dec 2022)
 Parts: 143 MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Chew Goon Motor/SKT8618E/01/12/2022 15:10
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Grille	0.00	0.00	*350.00 F Cag ✓
2	1		*Grille Emblem	0.00	0.00	*75.00 F mis ✓
3	1		*Grille Emblem Base Bracket	0.00	0.00	*38.00 F qn ✓
4	1		*Front Bumper	0.00	0.00	*650.00 F de ✓
5	10		*Front Bumper Clips	0.00	0.00	*40.00 F nu ✓
6	2		*Front Bumper Brackets	0.00	BT 0.00	✓ *250.00 F ? ✓
7	1		*Front Bumper Sponge	0.00	0.00	*100.00 F de ✓
8	1		*Front Bumper Reinforcement	0.00	0.00	*225.00 F ? bt ✓
9	1		*Front Bumper Center Air Grille	0.00	0.00	*76.00 F ? de ✓
10	1		*Front Bumper Sensor	0.00	0.00	*135.00 F nu ✓
11	4		*Front Bumper Sensor Holders	0.00	0.00	*100.00 F nu ✓
12	1		*Front Bumper Top Core	0.00	BR 0.00	✓ *150.00 F ? ✓
13	1		*Front Bumper Top Beam	0.00	0.00	*220.00 F ? nu ✓
14	1		*Front Bumper Inner Side Cores	0.00	BR 0.00	45 ✓ *90.00 F ? ✓
15	2		*Front Bumper Top Retainers	0.00	0.00	*50.00 F dig ✓
16	1		*Front Bumper Inner Collision Preventive Sensor	0.00	0.00	*135.00 F ? nu ✓
17	1		*Front Bumper Inner Collision Preventive Sensor Module	0.00	0.00	*1,320.00 F ? wa ✓
18	1		*Front Bumper Emblem	0.00	0.00	*30.00 F nu ✓
19	1		*Front Bumper Top Rubber Seal	0.00	0.00	*30.00 F de ✓
20	1		*Front Bumper Number Plate Holder	0.00	0.00	*80.00 F de ✓
21	2		*Headlamps	0.00	0.00	*2,900.00 F ? wa ✓
22	1		*Support Panel	0.00	0.00	*275.00 F ? bt ✓
23	1		*Air Con Condenser	0.00	0.00	*540.00 F bt ✓
24	1		*Air Con Condenser Side Air Guide	0.00	0.00	*120.00 F ? wa ✓
25	1		*Turbo Inter-Cooler	0.00	0.00	*450.00 F ? bt ✓
26	1		*Radiator	0.00	0.00	*590.00 F ? bt ✓
27	1		*Bonnet	0.00	0.00	*800.00 F R ✓
28	1		*Front Number Plate	0	0.00	*45.00 FS Cag ✓

=Franchise part. S=SpcNett.

Sub Total (\$\$)	9,864.00
+ Margin on L,N Items 10.00% (\$\$)	981.90
Total Parts (\$\$)	10,845.90

Chew Goon Motor/SKT8618E/01/12/2022 15:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

8634
 +10%
 9497.40 + 45 nett

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To Conduct Electrical Check, Focus Headlamp	New	30.00 ✓
2	To Remove / Refit Air Con Condenser & Refill Air Con Gas	New	100.00 ✓
3	To Remove / Refit, Radiator System, Bleed, Refill Coolant	New	50.00 ? ✓
4	Labour Charge - Panel Beating, Repairing of Front Chassis, Inner Panel, Front Fender & Part Replacement	New	600.00 500
5	To Respray Affected Areas	New	1,400.00 600
Gross Labour Cost (\$)			2,180.00

Chew Goon Motor/SKT8618E/01/12/2022 15:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1280

Tanfiki 97495749
Not Authorised Extra
04 days 02/12/22.
1/5 Barry after repair

10,822.40

L/S - 8657.92
= 8650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: