

GBK352S.

Toyota Dyna. 2982 cc

JTFAT35YX01C214632

TPAXA.

Xiao Tong

Front Bumper.	Dented	689.40. ✓
Headlamp RH.	Cut	727.10. ✓
Front RH Door.	Repairs	1485.40. ✗
Front RH Door Weatherstripe.	} not na	228.10. ✗
Front RH Door Hinge.		112.10. ✗
Front RH Door Company Detail Sticker.	} na	30(SN) ✓
Front RH Door Advertisement Sticker.		380(SN) 250(SN)
Front RH Step Garish.	Cut	245.90. ✓

1662.40 S.N: 280

1246.80

GBK35025.

Panel Beating

Spray Painting.

Wiring

To apply tuff coat.

To transfer door fittings.

860

~~600~~ 400

~~600~~ 400

~~50~~ 30

~~100~~ 30

150. x

Total 2386.80

L/s: 1-9K.

03 Day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: