



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS/ASM22012052/Aqp3e2

10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

Date: 27/02/2023

ATTN: LOH CYNTHIA

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 9823S	Veh. Inspected	GBK 3502S
Policy No.	VFX/P2413997	Coverage (\$)	0.00
Claim No.	S2M04FQY	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	01/12/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTFAT35YX0K214632	Colour	WHITE
Odometer	78106 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	ROVELO	6 mm
L/H Front Tyre	195 R15C	ROVELO	6 mm
R/H Rear Tyre	185 R12C	FALKEN	6 mm
L/H Rear Tyre	185 R12C	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/11/2022	Inspection Date	15/12/2022
Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**