



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authored

16 January 2023

2/12/22
1/5 \$8500
10 days.

REG NO.: SJQ 7370 C
MAKE/MODEL: MITSUBISHI LANCER

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
Nett	EST ITEMS	
1	Rear windscreen moulding	\$ 11 105.00 X
1	Rear boot lid	\$ 725.00 /
2	Rear boot dampers	\$ 11 242.00 X
2	Rear boot hinges	\$ 11 144.00 X
1	Rear boot inner trim	\$ Torn 158.00 /
1	Rear boot inner trim clip (1 set)	\$ 38.00 /
2	Rear boot lamps	\$ 372.00 /
1	Rear boot lock	\$ Bent 88.00 /
1	Rear boot lock catch	\$ Bent 65.00 /
1	Rear boot rubber	\$ 142.00 /
1	Rear boot top spoiler	\$ R 894.00 X
1	Rear boot third brake light	\$ 126.00 /
2	Rear taillamps	\$ 970.00 /
2	Rear taillamp panels	\$ 370.00 X
1	Rear end panel	\$ Body 558.00 /
1	Rear end panel inner garnish	\$ Torn 145.00 /
1	Rear smart keyless sensor	\$ 186.00 /
2	Rear bumper brackets	\$ Bent 130.00 /
1	Rear bumper beam	\$ Bent 105.00 /
2	Rear bumper reflectors	\$ 11 90.00 X
1	Rear bumper reinforcement	\$ 11 225.00 /
2	Rear bumper side retainers	\$ Bent 97.00 /
1	Rear bumper tow hook cover	\$ 38.00 X
1	Rear floor panel	\$ Cracked 955.00 /
1	Rear floor board	\$ Torn 203.00 /
2	Rear exhaust mountings	\$ 11 76.00 X
1	Rear fender	\$ R 895.00 X
1	Rear exhaust heat shield	\$ Bent 190.00 /
1	Rear fender inner trim nls	\$ Torn 382.00 /
289		\$ 8,714.00
	Less 10%	\$ 871.40
		\$ 7,842.60

SPECIAL NETT ITEMS

1	Rear windscreen sealant	11	\$	80.00	X
1	Rear bumper	7.5	\$	1,200.00	/
1	Rear bumper lower spoiler	2.5	\$	680.00	/
1	Rear number plate with holder	surf	\$	50.00	40
1	Rear reverse sensor (1 set)	shrub	\$	350.00	200
1	Rear exhaust silencer	R	\$	1,600.00	X
1 set	Rear reverse camera	shrub	\$	300 S/N	✓
1 set	Rear floor panel insulator	rec	\$	120 S/N	✓
			\$	3,960.00	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30
2	To remove and refit inner garnishes.	\$	180.00	80
3	To remove and refit rear reverse sensor.	\$	150.00	50
4	To transfer boot lid mechanism and wiring assembly.	\$	80.00	60
5	To remove and refit rear windscreen glass.	\$	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	80
7	To apply undercoating.	\$	150.00	80
8	Panel beating.	\$	1,800.00	1400
9	To re-spray painting on the affected areas.	\$	1,800.00	1200
		\$	4,570.00	

GRAND TOTAL :

\$ 16,372.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5767
102
519030
2540
2980
10710.3