

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI22012055/Rqy3m4	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	01/02/2023	
			Co	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMK 5155S	Veh. Inspected		SG 5075P	
	Policy No.	P10546206R01	Coverage (\$)		0.00	
	Claim No.	C10018848/CD	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		01/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	VOLVO B9TL 9.4L AUTO	c.c		9364	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	YV3S4P924GA177117	Colour		GREEN	
	Odometer	454713 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	GOODYEAR		8 mm	
	L/H Front Tyre	275/70 R22.5	GOODYEAR		8 mm	
	R/H Rear Tyre	275/70 R22.5 (D/D)	GOODYEAR		8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D/D)	GOODYEAR		8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	24/11/2022	Inspection Date		02/12/2022	
	Survey held at 154 GUL CIRCLE SINGAPORE 629611					
	Repairer	irer BOXFRESH PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: