



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel : 64585441 Fax : 64553470

Vehicle No : SG5075P

Accident date : 24/11/2022

Model No : VOLVO

Registered owner : Go Ahead Singapore Pte Ltd

B9TL-9.4 D AUTO TURBO ABS (A)

Date of Estimates : 02/12/22

Ref : BF-IC-1105

Raner
4p 90010068

2 days

02/12/22 @ 1655

Reqs after repair

Total Charge

Replaced and repair (Estimated 2 Days)

- a) Repair O/S deflector
- b) Repair Battery Compartment panel
- c) Repair O/S bumper
- d) Sand, Putty and make good surface of affected parts
- e) Painting of all affected parts.

Total charges ~~S\$800~~ 650

GST S\$56

Total Bill S\$ 856

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: