

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 18/01/2023

User ID : PohSuan

**Section A - Accident Details**

Registration Number	SHF95A
Case Reference Number	TAX/11/22/2060
Registration Date	1/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIM GUAN CHOON (LIN YUANJUN)
Type of Accident	Side Swipe
Accident Date and Time	30/11/2022 5:00 PM
Accident Reported Date and Time	1/12/2022 11:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117002
Special Instruction to ARC, if any	TP/LEFT PORTION
Prepared Date and Time	1/12/2022 1:57 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$1,116.00	\$600.00
Total Spare Part Cost	\$4,793.15	\$1,733.70
Total Other Cost	\$620.00	\$200.00
<b>TOTAL COST</b>	<b>\$7,543.15</b>	<b>\$2,933.70</b>
<b>Lump Sum Total</b>	<b>\$7,550.00</b>	<b>\$2,950.00 (L/S)</b>
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / China Taiping
ARC / Surveyor Sign Off Date	02/12/2022 2:27 PM	02/12/2022 11:28 AM
Signature		
Remarks		L/S repair. Resurvey after paint.

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2301-0251	<b>Invoice Number</b>	
<b>Quotation Date</b>	18.01.2023	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR LH PORTION	\$1,014.00	\$400.00
<b>Total Labour</b>	<b>\$1,014.00</b>	<b>\$400.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY DOOR HANDLE	\$180.00	\$50.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,116.00</b>	<b>\$600.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$620.00</b>	<b>\$200.00</b>

**Part 4 - Spare Parts / Material Usage**

<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>
		7586047900	MOULDING ASSY, BODY ROCKER PANEL , LH	0.00	\$649.10	0.00	\$0.00	Replace	Not Given
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	Replace
			STICKER STRIDES TAXI ( DOOR )	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6872012151	HINGE ASSY, FRONT DOOR , UPPER LH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given
		6874012120	HINGE ASSY, FRONT DOOR , LOWER LH	0.00	\$120.00	0.00	\$0.00	Replace	Not Given
		6980221010	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	0.00	\$257.80	0.00	\$0.00	Replace	Not Given
		8572047140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given
		6921047051A1	DOOR OUTER HANDLE FRONT , LH	0.00	\$423.20	0.00	\$0.00	Replace	Not Given
		7572047040	MOULDING ASSY, FRONT DOOR BELT, LH	0.00	\$99.90	0.00	\$0.00	Replace	Not Given
		6700447210	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace
		6876020122	HINGE ASSY, REAR DOOR , UPPER LH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given

X nn  
√ dd  
√ nec  
X  
X } nn  
X  
X } nn  
X  
X  
√ cra  
X nn

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/01/2023

User ID : PohSuan

		6878052031	HINGE ASSY, REAR DOOR , LOWER LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X	} nn
		8571047150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X	
		6980447020	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given	X	
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X	} nn
		7574047040	MOULDING ASSY, REAR DOOR BELT, LH	0.00	\$123.00	0.00	\$0.00	Replace	Not Given	X	
		692114-7021A1	DOOR OUTER HANDLE REAR , LH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X	
Total					\$7,569.90		\$2,167.13				

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	2,167.13	
	-20%	
	1733.70	L/S \$2,950/-
+	400.00	
+	800.00	
	2,933.70	