



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SNB 9600H

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
10	CLIP @\$1.20	NECESSARY	12.00
1	COVER-RR BUMPER	DEFORMED	448.30
1	LAMP ASSY-SIDE T/SIG & REAR, RH	CRACKED	511.50
	LESS 25% DISCOUNT		-242.95
			728.85
	<b><u>LABOUR</u></b>		
	TO CARRY OUT ACCIDENT BODY REPAIRS.		840.00
	TO SPRAY PAINT ON DAMAGED PORTIONS (BUMPER/TAILGATE).		560.00
	TO REPAIR REAR BACK PANEL.		420.00
			1,820.00
	<b>GRAND TOTAL</b>		<b>2,548.85</b>

<b>RECOMMENDED COST OF REPAIRS</b>	<b>2,548.85</b>
<b>LESS EXCESS</b>	<b>-350.00</b>
<b>NETT LIABILITY</b>	<b>2,198.85</b>

Report Ref No. CC2/MIDA22012061/Epe2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.