

STRIDES

AUTOMOTIVE

RECEIVED
12/05/23

Strides Automotive Services Pte. Ltd.
2 Tanjong Katong Road, Tower 3, Paya
Lebar Quarter, #08-01, Singapore 437161
Tel: 65 69083530 Fax: 65 69083592

Customer Code: 3000130

Ministry of Defence c/o Financial Services Centre
MR TAN KIEN KEONG, DONALD
Block Unit #15-01
DTTB FINANCIAL SERVICES CENTRE

SINGAPORE 109681

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : EV230500075
Date : 10.05.2023
Vehicle No. : 46166
Your Ref No. : CM/3000454445
Our Ref No. : 21264222
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
Others					
MAINTENANCE OF SAF ADMINISTRATIVE VEHICLES CONTRACTS NO: 8020200213 AMBULANCE:MB SPRINTER 515CDI/4325, FOR SPECIAL OPS MID 46166 (GRP B) SUNGEI GEDONG QUOTATION REF: C24/DEC22/QY2068	0.00	\$ 0.00	0.00	\$ 0.00	\$ 0.00
REAR RH DOOR ASSEMBLY	1.00	\$1880.00	0.00	\$ 0.00	\$ 1880.00
REAR LH DOOR ASSEMBLY	1.00	\$1986.00	0.00	\$ 0.00	\$ 1986.00
REAR RH DOOR HINGE ASSEMBLY (UPPER)	1.00	\$ 320.00	0.00	\$ 0.00	\$ 320.00
REAR RH DOOR HINGE ASSEMBLY (LOWER)	1.00	\$ 320.00	0.00	\$ 0.00	\$ 320.00
REAR LH DOOR HINGE ASSEMBLY (UPPER)	1.00	\$ 320.00	0.00	\$ 0.00	\$ 320.00
REAR LH DOOR HINGE ASSEMBLY (LOWER)	1.00	\$ 320.00	0.00	\$ 0.00	\$ 320.00
REAR RH TAIL LAMP ASSEMBLY	1.00	\$ 340.00	0.00	\$ 0.00	\$ 340.00
REAR LH TAIL LAMP ASSEMBLY	1.00	\$ 340.00	0.00	\$ 0.00	\$ 340.00
REAR BUMPER ASSEMBLY	1.00	\$ 660.00	0.00	\$ 0.00	\$ 660.00
REAR LICENCE PLATE GARNISH	1.00	\$ 60.00	0.00	\$ 0.00	\$ 60.00
REAR TOP STICKER (RED AMBULANCE WORDING)	1.00	\$ 120.00	0.00	\$ 0.00	\$ 120.00
REAR RH/LH DOOR GLASS MIDDLE STICKER (RED CROSS)	1.00	\$ 130.00	0.00	\$ 0.00	\$ 130.00
REAR RH/LH DOOR TRI-COLOUR STICKER	1.00	\$ 260.00	0.00	\$ 0.00	\$ 260.00
REAR RH/LH DOOR PRIVACY STICKER	2.00	\$ 44.00	0.00	\$ 0.00	\$ 88.00
PAINT MATERIAL	2.00	\$ 150.00	0.00	\$ 0.00	\$ 300.00
LABOUR:	0.00	\$ 0.00	0.00	\$ 0.00	\$ 0.00
REAR RH/LH DOORS DENTED	12.00	\$ 39.07	0.00	\$ 0.00	\$ 468.84
REMOVE & INSTALL REAR RH/LH DOOR,	0.00	\$ 0.00	0.00	\$ 0.00	\$ 0.00

Payment Instructions

By Cheque: Crossed and made payable to "Strides Automotive Services Pte. Ltd." with invoice no. indicated on the reverse side. No receipt will be issued unless requested.

By Bank Transfer:

Account Name : Strides Automotive Services Pte. Ltd.
Bank Name : DBS Bank Ltd - SGD
Bank Account No.: 018-008617-4
Swift Code : DBSSSGSG

 Tan Yuwei
Manager
Fleet Maintenance



Authorised Signature
for Strides Automotive Services Pte. Ltd.

STRIDES

AUTOMOTIVE

Strides Automotive Services Pte. Ltd.
2 Tanjong Katong Road, Tower 3, Paya
Lebar Quarter, #08-01, Singapore 437161
Tel: 65 69083530 Fax: 65 69083592

Customer Code: 3000130

Ministry of Defence c/o Financial Services Centre
MR TAN KIEN KEONG, DONALD
Block Unit #15-01
DTTB FINANCIAL SERVICES CENTRE

SINGAPORE 109681

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : EV230500075
Date : 10.05.2023
Vehicle No. : 46166
Your Ref No. : CM/3000454445
Our Ref No. : 21264222
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount		Amount
REAR RH/LH DOOR HINGE ASSEMBLY (UPPER & LOWER) & TO ALIGN						
REAR RH/LH TAIL LAMP ASSEMBLY CRACKED	2.00	\$ 39.07	0.00	\$ 0.00	\$	78.14
REMOVE & INSTALL REAR RH/LH TAIL LAMP ASSEMBLY	0.00	\$ 0.00	0.00	\$ 0.00	\$	0.00
REAR BUMPER DAMAGED	2.00	\$ 39.07	0.00	\$ 0.00	\$	78.14
REMOVE & INSTALL REAR BUMPER ASSEMBLY	0.00	\$ 0.00	0.00	\$ 0.00	\$	0.00
REAR LICENCE PLATE GARNISH CRACKED	0.50	\$ 39.07	0.00	\$ 0.01	\$	19.54
REMOVE & INSTALL REAR LICENCE PLATE GARNISH	0.00	\$ 0.00	0.00	\$ 0.00	\$	0.00
REAR RH/LH DOOR DENTED	8.00	\$ 39.07	0.00	\$ 0.00	\$	312.56
INSTALL REAR TOP STICKER (RED AMBULANCE WORDING), REAR RH/LH DOOR GLASS MIDDLE STICKER (RED CROSS), REAR RH/LH DOOR TRI-COLOUR STICKER & REAR RH/LH DOOR PRIVACY STICKER	0.00	\$ 0.00	0.00	\$ 0.00	\$	0.00
RH REAR BODY PANEL DENTED	8.00	\$ 39.07	0.00	\$ 0.00	\$	312.56
REMOVE & INSTALL, PANEL BEAT RH REAR BODY PANEL DENTED	0.00	\$ 0.00	0.00	\$ 0.00	\$	0.00
SPRAY PAINT ON REPAIRED AREAS BODY	12.00	\$ 39.07	0.00	\$ 0.00	\$	468.84
PUTTY & REPRAY ON REAR RH/LH DOORS, REAR RH/LH HINGE ASSEMBLY (UPPER & LOWER) AND RH REAR BODY PANEL	0.00	\$ 0.00	0.00	\$ 0.00	\$	0.00
TOWING SERVICE:	0.00	\$ 0.00	0.00	\$ 0.00	\$	0.00
TO PROVIDE TOWING SERVICE FOR ABOVE VEHICLE FROM SUNGEI GEDONG CAMP TO	1.00	\$ 106.94	0.00	\$ 0.00	\$	106.94

Payment Instructions

By Cheque: Crossed and made payable to "Strides Automotive Services Pte. Ltd." with invoice no. indicated on the reverse side. No receipt will be issued unless requested.

By Bank Transfer:

Account Name : Strides Automotive Services Pte. Ltd.
Bank Name : DBS Bank Ltd - SGD
Bank Account No.: 018-008617-4
Swift Code : DBSSSGSG

PAID
15/05/23

Tow: 1000181662

MAINT: 1000181663

LAB: 1000181664

Tan Yuwei
Manager
Fleet Maintenance



Authorised Signature
for Strides Automotive Services Pte. Ltd.

STRIDES

AUTOMOTIVE

Customer Code: 3000130

Ministry of Defence c/o Financial Services Centre
MR TAN KIEN KEONG, DONALD
Block Unit #15-01
DTTB FINANCIAL SERVICES CENTRE
SINGAPORE 109681

Strides Automotive Services Pte. Ltd.
2 Tanjong Katong Road, Tower 3, Paya
Lebar Quarter, #08-01, Singapore 437161
Tel: 65 69083530 Fax: 65 69083592

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : EV230500075
Date : 10.05.2023
Vehicle No. : 46166
Your Ref No. : CM/3000454445
Our Ref No. : 21264222
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
STRIDES WORKSHOP. TO PROVIDE TOWING SERVICE FOR ABOVE VEHICLE FROM STRIDES WORKSHOP TO SUNGEI GEDONG CAMP	1.00	\$ 106.94	0.00	\$ 0.00	\$ 106.94

TOTAL BEFORE GST	\$	9,396.50
ADD GST @ 08 %	\$	751.72
GRAND TOTAL	\$	10,148.22

Payment Instructions

By Cheque: Crossed and made payable to "Strides Automotive Services Pte. Ltd." with invoice no. indicated on the reverse side. No receipt will be issued unless requested.

By Bank Transfer:

Account Name : Strides Automotive Services Pte. Ltd.
Bank Name : DBS Bank Ltd - SGD
Bank Account No.: 018-008617-4
Swift Code : DBSSSGSG



 Tan Yuwei
Manager
Fleet Maintenance

Authorised Signature
for Strides Automotive Services Pte. Ltd.