

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22012073/TVP3E2**Date:** 29/03/2023REFERENCEInsured/Claimant: SOH CHEE CHEONG REUBEN(SU ZHIZHONG, REUBEN) Policy No: 1700072065-05  
Date of Loss: 21/11/2022 Nature of Claim: OD Claim No: 4876089887SGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT790E**  
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK047766  
Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: WAUZZZF57JA038760  
Colour: Grey Odometer: 44515 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$128,000.00  
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: YesCONDITION OF TYRESFront Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,818.00	8,847.52	3,970.48	30.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,032.00	6,642.00	5,390.00	44.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,850.00</b>	<b>15,489.52</b>	<b>9,360.48</b>	<b>37.67</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	24,250.00	14,889.52	9,360.48	38.60
<b>+ GST 8.00/8.00% (S\$)</b>	1,940.00	1,191.16	748.84	38.60
<b>Nett Amount (S\$)</b>	<b>26,190.00</b>	<b>16,080.68</b>	<b>10,109.32</b>	<b>38.60</b>

INSPECTIONDate of Assignment: 02/12/2022  
Date Inspected: 01/12/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 8.0 days**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Bent	3,977.00 FS	*3,181.60 FS
2	1		*FRONT OUTER DOOR SEAL - RH	Necessary	247.00 FS	*197.20 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*FRONT DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS
7	1		*FRONT DOOR CHROME TRIM - RH	Necessary	171.00 FS	*136.40 FS
8	1		*FRONT TYRE PRESSURE DATA PLATE	Necessary	41.00 FS	*32.40 FS
9	1		*REAR DOOR - RH	Bent	3,977.00 FS	*3,181.60 FS
10	1		*REAR OUTER DOOR SEAL - RH	Necessary	247.00 FS	*197.20 FS
11	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
12	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
13	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
14	1		*REAR DOOR CATCH - RH	Loose	134.00 FS	*106.80 FS
15	1		*REAR DOOR SIDE MEMBER TRIM - RH	Repair	872.00 FS	*- FS
16	1		*REAR ATTACHMENT PARTS	Necessary	136.00 FS	*108.80 FS
17	1		*ADHESIVE TAPES	Necessary	221.00 FS	*176.80 FS
18	1		*REAR ALUMINIUM RIM	Cut	1,889.00 FS	*1,511.20 FS
19	1		*REAR ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
20	1		*SUNDRIES	Necessary	500.00 FS	*14.56 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>12,818.00</b>	<b>8,847.52</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	900.00	560.00
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	460.00	360.00
3	TO RESPRAY RHS FRONT DOOR, DOOR HANDLE, RHS REAR DOOR, RHS SILL PANEL TRIM, RHS REAR FENDER AND REAR BUMPER	New	5,500.00	2,750.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	380.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	192.00
6	TO DISMANTLE AND RENEW RHS FRONT DOOR, RHS REAR DOOR AND RHS SILL PANEL TRIM TO REPAIR RHS REAR FENDER. TO REMOVE AND REINSTALL REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,500.00	2,500.00
<b>Gross Labour Cost (\$)</b>			<b>12,032.00</b>	<b>6,642.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >