



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01051/2022/EQ
DATE : 23-Nov-22
WIP : 51823

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/11/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : DR SOH CHEE CHEONG REUBEN (SU ZHIZHONG, REUBEN)
ADDRESS : 7A HOLLAND HILL
#04-08
SINGAPORE 278732
TELEPHONE : HP +65 96473700
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700072065-05
VEHICLE NO : **SLT 790 E**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 1/11/2017
ENGINE NO : CVK 047766
CHASSIS NO : WAUZZZF57JA038760
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Nov-22
PLACE OF ACCIDENT : ORANGE GROVE ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 790 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 900.00	
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 460.00	
3	TO DISMANTLE AND RENEW RHS FRONT DOOR, RHS REAR DOOR AND RHS SILL PANEL TRIM. TO REPAIR RHS REAR FENDER. TO REMOVE AND REINSTALL REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	
4	TO REPRAY RHS FRONT DOOR, DOOR HANDLE, RHS REAR DOOR, RHS SILL PANEL TRIM, RHS REAR FENDER AND REAR BUMPER.	\$ 5,500.00	
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 380.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	
TOTAL LABOUR CHARGES		: \$ 12,032.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 790 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1	\$ 3,977.00	
2	FRONT OUTER DOOR SEAL - RH	1	\$ 247.00	
3	BONDING AGENT	1	\$ 51.00	
4	CLEANING SOLUTION	1	\$ 74.00	
5	APPLICATOR	1	\$ 9.00	
6	FRONT DOOR CATCH - RH	1	\$ 134.00	
7	FRONT DOOR CHROME TRIM - RH	1	\$ 171.00	
8	FRONT TYRE PRESSURE DATA PLATE	1	\$ 41.00	
9	REAR DOOR - RH	1	\$ 3,977.00	
10	REAR OUTER DOOR SEAL - RH	1	\$ 247.00	
11	BONDING AGENT	1	\$ 51.00	
12	CLEANING SOLUTION	1	\$ 74.00	
13	APPLICATOR	1	\$ 9.00	
14	REAR DOOR CATCH - RH	1	\$ 134.00	
15	REAR DOOR SIDE MEMBER TRIM - RH	1	\$ 872.00	
16	REAR ATTACHMENT PARTS	1	\$ 136.00	
17	ADHESIVE TAPES	1	\$ 221.00	
18	REAR ALUMINIUM RIM	1	\$ 1,889.00	
19	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
20	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 12,818.00	
TOTAL LABOUR CHARGES		:	\$ 12,032.00	
GRAND TOTAL		:	\$ 24,850.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT