



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22012076/Tny3e2 Date: 03/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SND 3009U	Veh. Inspected	SMR 882Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS22/3366	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	01/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 520I	c.c	1997	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WBA5A32010D334478	Colour	GOLD	
Odometer	135076 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	PIRELLI	6 mm	
L/H Front Tyre	225/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2022	Inspection Date	02/12/2022	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)REGISTRATION DATE: 28 MAY 2014 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	