

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SMR882Y

Make/Model : BMW 520I

Chassis No: WBA5A32010D334478

Accident date : 29.11.2022

TP Liberty
Hui Rong

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Rear bootlid <i>Dented</i>	1	\$ 1,771.00 ✓
2	Rear bootlid hinges @ \$132.00 <i>new</i>	2	\$ 264.00 +
3	Rear bootlid upper lock <i>Damaged</i>	1	\$ 238.70 ✓
4	Rear bootlid lower catch <i>new</i>	1	\$ 180.00 +
5	Rear bootlid weather strip <i>lt</i>	1	\$ 170.00 ✓
6	Rear bootlid centre logo <i>3 new</i>	1	\$ 78.00 ✓
7	Rear bootlid "520I" emblem	1	\$ 78.00 ✓
8	Rear bootlid insulation <i>new</i>	1	\$ 125.00 +
9	Rear bootlid LH reflector <i>cracked</i>	1	\$ 412.50 335.
10	Rear LH lamp <i>cracked</i>	1	\$ 649.00 ✓
11	Rear LH lamp housing <i>3 new</i>	1	\$ 808.00 +
12	Rear LH lamp lower garnish <i>new</i>	1	\$ 30.00 +
13	Rear bumper <i>Distorted</i>	1	\$ 1,800.00 1555
14	Rear bumper side holder @ \$159.50 <i>new</i>	2	\$ 319.00 +
15	Rear bumper reflector @ \$89.60 <i>LH cracked</i>	2	\$ 179.20 89.60.
16	Rear bumper inner top garnish <i>new</i>	1	\$ 60.50 +
17	Rear bumper inner centre garnish <i>cracked</i>	1	\$ 77.00 ✓
18	Rear bumper reinforcement <i>Dented</i>	1	\$ 792.00 ✓
19	Rear bumper bracket @ \$260.00 <i>new</i>	2	\$ 520.00 +
20	Rear bumper centre lower garnish <i>cracked</i>	1	\$ 135.00 ✓
21	Rear bumper towing hook cover <i>Missing</i>	1	\$ 33.00 ✓
22	Rear end panel <i>Dented</i>	1	\$ 850.00 ✓
23	Rear end panel top garnish <i>cracked</i>	1	\$ 115.00 ✓
24	Rear exhaust chrome @ \$150.00 <i>2nd</i>	2	\$ 300.00 200.
25	Rear exhaust pipe <i> Bent</i>	1	\$ 1,730.00 1350.
26	Rear exhaust pipe mounting @ \$30.00 <i>new</i>	2	\$ 60.00 +
27	Rear spare tyre top board <i>new</i>	1	\$ 760.00 +
28	Rear bumper lower lip <i>Def-d</i>	1	\$ 235.80 ✓
			\$ 12,770.70
Less 5% Disc			\$ 638.54
Total			\$ 12,132.17

8852-10.

8409.49.

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SMR882Y

Make/Model : BMW 520I

Chassis No: WBA5A32010D334478

Accident date : 29.11.2022

No	DESCRIPTION	Qty	Amount (\$S)
Special Nett Items			
1	Rear bumper reverse sensor @ \$299.00 <i>2 pieces damaged</i>	4	\$ 1,196.00 <i>598</i>
2	Rear bumper reverse sensor wire (1 set) <i>short new</i>	1	\$ 280.00 <i>x.</i>
3	Rear bumper clips (1 set) <i>new</i>	1	\$ 50.00 <i>30</i>
4	Rear bootlid insulation clips (1 set) <i>new</i>	1	\$ 75.00 <i>x.</i>
		Total	\$ 1,601.00

Labour Cost			
1	To supply rear end panel inner sealant		\$ 200.00 <i>60.</i>
2	Remove & reinstall bootlid inner garnish		\$ 200.00 <i>80.</i>
3	Remove & reinstall reverse sensor		\$ 200.00 <i>50</i>
4	Remove & reinstall exhaust pipe		\$ 400.00 <i>120</i>
5	Remove, replace & repair consistent to the accident		\$ 1,500.00 <i>1000</i>
6	Respray painting		\$ 1,300.00 <i>750</i>
7	Tuff kote		\$ 100.00 <i>80.</i>
		Total	\$ 3,900.00
		Grand Total	\$ 17,633.17

8 Remove and reinstall upholstery. *150*

80.

2470

11257.90

total 11507.49

c/s: 9.2k. 9000

08 Days

9.2k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: