

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

NOT Withheld
11 Pmp @ 3400/h
Pehony Hwa Pany

Shirley Choo Li Lan
Blk 716 #04-43
Clementi West St 2
Singapore 120716

Survey on 6.12.22 @ 10.30am

Vehicle No : SBU 3232 T
Make : Toyota Vios
Year : 2016

MAFBT913

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s door assy	1012.60	1,138.70
1 pc	Front o/s door inner trim board	?	985.70
1 pc	Front o/s door glass regulator	?	287.60
1 pc	Front o/s door glass regulator motor	505	704.20
1 pc	Front o/s door inner lock	?	603.50
1 pc	Front o/s door weatherstrip	?	225.30
1 set	Front o/s door frame black sticker	?	75.10
1 pc	Rear o/s door assy	984.90	1,295.60
1 pc	Rear o/s door frame black sticker	?	75.10
1 pc	Rear o/s door weatherstrip	?	205.10
1 pc	Rear o/s door inner trim board	?	955.10
1 pc	Rear o/s door glass regulator	?	287.60
1 pc	Rear o/s door glass regulator motor	?	704.60
1 pc	Rear o/s door lower hinge	?	155.20
1 pc	O/S door centre pillar	repair	487.10
1 pc	Rear axle	repair	2,882.50
1 pc	Rear o/s shock absorber	?	149.10
1 pc	Rear o/s hub assy	?	804.50
			\$12,021.60
		Less 25 %	\$3,005.40
			\$9,016.20

S. Nett

1 pc	Rear o/s tyre rim	280.00	500.00
20 pcs	Rear bumper clip	2.00	40.00
			\$540.00
Door insulation x2 @ 150.00			300.00
3006 rear			200.00
		balance c/f	\$9,556.20

9856.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SBU 3232 T

balance b/f \$9,556.20

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,200.00	500
To putty & spray paint on accident affected portion.	\$1,200.00	800
Check/reconnect wiring.	\$45.00	20
To spray anti rust on accident affected portion.	\$120.00	60
Remove/refit both n/s door mechanism, glass to new door	\$200.00	120
Remove/renew rear o/s undercarriages.	\$350.00	X
Check and realign wheel alignment	\$60.00	✓
Total	<u>\$12,731.20</u>	

LK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: