

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SLK LOGISTICS PTE LTD

8A ADMIRALTY ST #05-24/25

SINGAPORE 757437

Contact : 90100353, 83102816

TAX INVOICE

TP A x A

Repair Code : CLM15752

Date in : 30/11/2022

Xiao by

Vehicle Num. : GBD4318M

Model : MITSUBISHI CANTER FEA01BR1SDEB (CBU)

Chassis/Eng# : FEA01BA00401/4P10B29509

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR CHASSIS MEMBER LH <i>Repr</i>	1	3219.10	<i>+</i> 3,219.10
REAR EXHAUST RUBBER MOUNTING <i>neu</i>	1	35.00	<i>+</i> 35.00
REAR EXHAUST SILENCER BOX <i>Dented</i>	1	980.00	<i>695</i> 980.00
REAR LH TAILLAMP ASSY <i>at</i>	1	369.00	<i>✓</i> 369.00
REAR NUMBER PLATE LAMP <i>neu</i>	1	128.00	<i>+</i> 128.00
REAR NUMBER PLATE PANEL <i>Bea</i>	1	150.00	<i>✓</i> 150.00
Subtotal before discount			4,881.10
Percentage discount <i>10%</i> <i>25%</i>			488.11
Sub-total 1			4,392.99
REAR CABIN FRAME PLATE (STEELS) <i>Dented</i>	1	2400.00	<i>1000</i> 2,400.00
REAR LH TAILLAMP BRACKET <i>Dented</i>	1	110.00	<i>✓</i> 110.00
REAR NUMBER PLATE <i>Dented</i>	1	25.00	<i>✓</i> 25.00
Subtotal before discount			2,535.00
Percentage discount 0%			0.00
Sub-total 2			2,535.00
Parts-total			6,927.99

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

30 ~~80.00~~

2w ~~800.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SLK LOGISTICS PTE LTD
8A ADMIRALTY ST #05-24/25
SINGAPORE 757437

Contact : 90100353, 83102816

TAX INVOICE

Repair Code : CLM15752

Date in : 30/11/2022

Vehicle Num. : GBD4318M

Model : MITSUBISHI CANTER FEA01BR1SDEB (CBU)

Chassis/Eng# : FEA01BA00401/4P10B29509

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

80 100.00

400 1,000.00

30 120.00

Labour Total

2,100.00

Parts & Labour Total

9,027.99

*** This is a computer-generated document which requires no signature.***

page 2

Adrian C
2/5 05/12/22

04 Days

Label: 2673

4/5: 2.1K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: