

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 05 Dec 2022

**Preliminary Advice**

Vehicle No	: SLH3410X	Accident Date	: 29/11/2022
Make	: KIA SORENTO	Policy No.	: MPC22P00252700
Assignment Date	: 02/12/2022	Excess	: S\$0.00
Date of Inspection	: 2/12/2022	Est. Duration of Repair	: 5
Inspection At	: YEW TEE AUTOMOBILE TECH PL		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,982.00
Revised Amount	:S\$	1,806.00
Check Items (Estimated)	:S\$	269.00
Total	:S\$	2,075.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	44,117.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,883.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Vehicle repair on part by part

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .