



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

Xiao Tong

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/01081/2022/EQ 5-Jan-23 GLORY 1 of 1 SCG 6608 K AUDI A5 SPORTBACK 2.0 TFS
Quantity	Description	Unit Price	Amount
Labours			
1	TO RENEW REAR WINDSCREEN. <i>Free</i>	S/N \$ 480.00	✓
2	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN. <i>Free</i>	S/N \$ 400.00	✓
3	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	150
Parts			
1	REAR WINDSCREEN <i>Free</i>	\$ 1,301.00	✓
2	PRIMER	\$ 22.00	✓
3	ADDITIONAL BRAKE LIGHT <i>Free</i>	\$ 642.00	✓
4	REAR WINDSCREEN SEALANT <i>Free</i>	\$ 200.00	✓
GRAND TOTAL		\$ 3,245.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Lj
Resurveyed
 Add 1 Day for the repairs
~~replacement~~ of end panel.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCG 6608 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	✓
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	1000 Add 250.
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END ? PANELLING.	\$	3,000.00	1100 + 550.
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 6,632.00</u>	