



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/01081/2022/EQ
DATE : 2-Dec-22
WIP : 53256

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/12/2022
YOUR INSURED VEH NO : SJU 5975 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MR KOH YOUNG KWANG
ADDRESS : BLK 81 BUKIT DRIVE
#03-04
SINGAPORE 587850
TELEPHONE : HP +65 96662813
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : GA526151/1
VEHICLE NO : **SCG 6608 K**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 1/2/2019
ENGINE NO : CVK 075803
CHASSIS NO : WAUZZZF51KA022295
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Nov-22
PLACE OF ACCIDENT : JUNCTION OF COMMONWEALTH AVE WEST/
CLEMENTI AVE 2



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCG 6608 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	✓
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	1000
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$	3,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 6,632.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCG 6608 K

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY			S/NETT	REMARKS
1	REAR BUMPER	1	\$		3,012.00	de ✓
2	REAR BUMPER FIXING PARTS	1	\$		273.00	?
3	REAR BUMPER SECURING STRIP	1	\$		249.00	re ✓
4	REAR BUMPER CHROME TRIM	1	\$		1,139.00	cut ✓
5	REAR BUMPER REFLECTOR - LH / RH	2	\$		92.00	X
6	REAR INNER TAIL LIGHT	1	\$		1,135.00	X
7	REAR BUMPER REINFORCEMENT BEAM	1	\$		1,131.00	?
8	REAR BUMPER SEAL - LH / RH	2	\$		32.00	?
9	REAR BUMPER GUIDE SECTION - LH / RH	2	\$		98.00	X
10	REAR BUMPER GUIDE SECTION - LH / RH UPPER	2	\$		52.00	X
11	REAR PARKING AID SENSOR - INNER / OUTER	2	\$		531.00	?
12	REAR PARKING AID SEAL RING	4	\$		10.00	re ✓
13	REAR BUMPER WIRING SET	1	\$		745.00	?
14	REAR LID	1	\$		4,103.00	bt ✓
15	REAR LID LOCK	1	\$		301.00	?
16	REAR LID LOCK COVER	1	\$		13.00	?
17	REAR LID FLAP GASKET	1	\$		263.00	?
18	REAR LID LOCK ACTUATOR WITH CAMERA PUSHBUTTON	1	\$		1,478.00	X
19	REAR LID STRIKER PLATE	1	\$		74.00	X
20	PACKING ADHESIVE	1	\$		21.00	re ✓
SUB TOTAL SPARE PARTS			:	\$	14,752.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCG 6608 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AUDI EMBLEM	1	\$ 163.00	<i>new</i>
22	"A5" INSCRIPTION	1	\$ 104.00	<i>new</i>
23	REAR NO PLATE	S/N	\$ 60.00	<i>bt</i>
24	SUNDRIES		\$ 400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 15,479.00	
TOTAL LABOUR CHARGES		:	\$ 6,632.00	
GRAND TOTAL		:	\$ 22,111.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 97495749
'WP' 8/12/22 @ 1015
Resurvey before paint
taufik@lkkauto.com
25 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT