



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile **CS3/SMO22007353/Eqy3-1**

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: ~~CS3/SMO22007353/Eqy3~~  
Date: ~~02/08/2022~~ 15/11/2022  
Code: SMO

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	SLN 8749E	<b>Veh. Inspected</b>	SNE 9985G
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2202608/LOR SYH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	<del>GRACE TEO</del> HWANG SHIANG YI	<b>Assign Date</b>	<del>02/08/2022</del> 15/11/2022

### 2. HWANG SHIANG YI Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

<b>Accident Date</b>	30/07/2022	<b>Inspection Date</b>	02/08/2022
<b>Survey held at</b>	No 1 Bukit Batok Crescent, 02-20 Wcega Plaza		
<b>Repairer</b>	GARAGE STAR PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.