



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 01/12/2022	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR053REH104558000	1ZRY332131	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO :SHF185Z ACC DATE:30/11/22 DRIVE IN:30/11/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON: 2 B BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR 3 B BP-MECH2 CONDUCT WHEEL ALIGNMNET 4 B BP-MECH2 REPL LH FRT UNDERCRRRIAGE PART 5 B BP-MECH2 REPL REAR LH UNDERCARRIAGE PART 6 S BP-SUBLET TRANSFER FRT AND REAR TYRE TO NEW RIM 7 Z BP-SLANT SUPPLY SEALANT (NETT) 8 B BP-LAB2 TRANSFER RH FRT AND REAR DOOR MECHANISM 9 B BP-LAB2 REPL ACC AFF PARTS AND PANEL 10 B BP-RES2 RESRPAY ACC AFF AREA 11 1 K52116-02270 SUPPORT, FR BUMPER S 12 2 K52119-02955 COVER, FR BUMPER L/C 13 3 K53802-02220 FENDER SUB-ASSY, FR 14 4 K53876-02680 LINER, FR FENDER, LH 15 5 K61602-02280 PANEL SUB-ASSY, QUAR				50 100.00
						198.00
						198.00
						792.00
						792.00
						160.00
						200.00
						792.00
						3168.00
						3608 396.00
			1.00	101.70		101.70
			1.00	633.80		633.80
			1.00	1081.20		1081.20
			1.00	270.50		270.50
			1.00	1369.30		1369.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 01/12/2022	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104558000	12RY332131	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	6	K67002-02470 PANEL SUB-ASSY, FR D <i>Panel</i>	1.00	1495.20		1495.20
17	7	K75922-02220 TAPE, BLACK OUT, NO. <i>4p 20010068</i>	1.00	57.20		57.20
18	8	K75924-02250 TAPE, BLACK OUT, NO. <i>8 days</i>	1.00	51.90		51.90
19	9	K67004-02430 PANEL SUB-ASSY, RR D <i>05/12/22 21410</i>	1.00	1481.90		1481.90
20	0	K75444-02A20 PLATE, LUGGAGE COMPT <i>Resy before paint</i>	1.00	42.30		42.30
21	1	K42450-02211 HUB & BRG ASSY, RR A <i>? xsvl</i>	1.00	1143.90		1143.90
22	2	K42611-02C80 WHEEL, DISC <i>? xsvl</i>	2.00	2390.80		4781.60
23	3	S43420-02A10 SHAFT ASSY, FR DRIVE <i>? xsvl</i>	1.00	1486.20		1486.20
24	4	K90080-36137 BEARING, RADIAL BALL <i>? bt</i>	1.00	129.10		129.10
25	5	K43502-02110 HUB SUB-ASSY, FR AXL <i>? bt</i>	1.00	311.40		311.40
26	6	K43330-09681 JOINT ASSY, LWR BALL <i>? xsvl</i>	1.00	283.60		283.60
27	7	K43212-02270 KNUCKLE, STEERING, L <i>? bt</i>	1.00	747.30		747.30
28	8	K48069-02260 ARM SUB-ASSY, SUSPEN <i>? xsvl</i>	1.00	873.80		873.80
29	9	K48520-8Z056 ABSORBER SET, SHOCK, <i>? bt</i>	1.00	523.40		523.40

28426

LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - To display damaged part(s) during resurvey		Customer's Signature		Charge Summary		Total	27,201.30
For & on behalf of Borneo Motors (Singapore) Pte Ltd		• Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Parts 16,865.30 Labour 10,176.00 Sublet 160.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00%	1,904.09
Acknowledged by Repairer Signature: _____ Date: _____				Less		0.00	
				Amount Due			29,105.39

Customer Copy



Reg No. : 196700086Z
 T Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no: 6631 1188

Supplementary

ESTIMATE

Account Details			Account No.		Customer Details			
First Capital Insurance Ltd Robinson Road 01 City House Singapore 068877 Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 14/12/2022					
Car	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053REH104558000		1ZRY332131	60	Shashitharan	06/12/2022 8.00		14/12/2022 18.00	
Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	1	S81150-02F31	HEADLAMP ASSY, LH <i>cm</i>		1.00	1105.20		1105.20
2	2	S53828-02210	PROTECTOR, FR FENDER <i>de</i>		1.00	119.50		119.50
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						1,224.70		
		Please acknowledge receipt of vehicle		Parts		GST 7.00%		
				Labour		85.73		
				Sublet		Less		
				Lubrication/Fluid		0.00		
				Others		0.00		
						Amount Due		
						1,310.43		