



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte Ltd
	Document No. 38068319	3 Media Close #01-03/06 Singapore 138498
	Document Date 14/12/2022	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	407188	18890	66TP/SLG8769J/301122

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104558000	1ZRY332131	60	Shashitharan	06/12/2022 8.38	14/12/2022 8.30

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SHF185Z ACC DATE:30/11/22 DRIVE IN:30/11/22 EXCESS: DATE-IN:06-12-22 DATE SURVEY:05/12/22 NO OF REPAIR DAYS:8 BY:rasul lkk AUTHORISED ON:06/12/22	*			50.00
2	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR	BP60			198.00
3	B	BP-MECH2 CONDUCT WHEEL ALIGNMENT	BP60			198.00
4	B	BP-MECH2 REPL LH FRT UNDERCARRIAGE PART	BP60			792.00
5	B	BP-MECH2 REPL REAR LH UNDERCARRIAGE PART	BP60			792.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
7	B	BP-LAB2 TRANSFER RH FRT AND REAR DOOR MECHANISM	*			792.00
8	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL	*			3168.00
9	B	BP-RES2 RESRPAY ACC AFF AREA	*			3608.00
10	L	BP-LPO TRANSFER TYRE TO NEW RIM AND CONDUCT BALANCING (PO	0239			160.00
11	1	K52116-02270 SUPPORT, FR BUMPER S	1.00	101.70		101.70
12	2	K52119-02955 COVER, FR BUMPER L/C	1.00	633.80		633.80
13	3	K53802-02220 FENDER SUB-ASSY, FR	1.00	1081.20		1081.20
14	4	S53876-02680 LINER, FR FENDER, LH	1.00	270.50		270.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 38068319	
	Document Date 14/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	407188	18890	66TP/SLG8769J/301122

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104558000	1ZRY332131	60	Shashitharan	06/12/2022 8.38	14/12/2022 8.30

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	5	K67002-02470 PANEL SUB-ASSY, FR D	1.00	1495.20		1495.20
16	6	K75922-02220 TAPE, BLACK OUT, NO.	1.00	57.20		57.20
17	7	K75924-02250 TAPE, BLACK OUT, NO.	1.00	51.90		51.90
18	8	K67004-02430 PANEL SUB-ASSY, RR D	1.00	1481.90		1481.90
19	9	K75444-02A20 PLATE, LUGGAGE COMPT	1.00	42.30		42.30
20	0	K42611-02C80 WHEEL, DISC	2.00	2390.80		4781.60
21	1	K90080-36137 BEARING, RADIAL BALL	1.00	129.10		129.10
22	2	K43502-02110 HUB SUB-ASSY, FR AXL	1.00	311.40		311.40
23	3	K43212-02270 KNUCKLE, STEERING, L	1.00	747.30		747.30
24	4	S48520-8Z056 ABSORBER SET, SHOCK,	1.00	523.40		523.40
25	5	S81150-02F31 HEADLAMP ASSY, LH	1.00	1105.20		1105.20
26	6	S53828-02210 PROTECTOR, FR FENDER	1.00	119.50		119.50

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	22,891.20
	Please acknowledge receipt of vehicle	Parts 12,933.20	GST 7.00%	1,602.38
		Labour 9,798.00	Less	0.00
		Sublet 160.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	24,493.58

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

**TOYOTA***Supplementary***ESTIMATE**

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 14/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR053REH104558000	1ZRY332131	60	Shashitharan	06/12/2022	8.00	14/12/2022	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	1	S81150-02F31 HEADLAMP ASSY, LH	1.00	1105.20		1105.20
2	2	S53828-02210 PROTECTOR, FR FENDER	1.00	119.50		119.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle 	Parts 1,224.70	1,224.70
		Labour 0.00	GST 7.00% 85.73
		Sublet 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 1,310.43

Company Copy

Customer

Vehicle ident no.

Repair order no.
R002023Technician
61Date/Time
13.12.22 12:53License plate no.
SLG8769J

First reg. date

Model
TOYOTA ALTIS (ZRE171R)Odometer reading: km/miles
408203

Complaints or reason for alignment check

			Before	Target Data		Actual
Rear axle	Camber	left	-1°36'	-1°26'	+/-0°30'	-1°20'
		right	-1°32'			-1°33'
		cross	-0°04'	0°00'	+/-0°30'	0°13'
	Toe	left	0°13'	0°06'	+/-0°08'	0°05'
		right	0°05'			0°06'
		total	0°18'	0°12'	+/-0°16'	0°11'
	Geometrical driving axis		0°04'	0°00'		-0°01'
Front axle	Camber	left	-0°55'	-0°35'	+/-0°45'	-0°56'
		right	-0°30'			-0°30'
		cross	-0°25'	0°00'	+/-0°30'	-0°26'
	Caster	left	3°28'	2°52'	+/-0°45'	3°21'
		right	2°56'			2°59'
		cross	0°32'	0°00'	+/-0°30'	0°22'
	SAI	left	13°06'	12°12'		12°45'
		right	12°36'			12°34'
		cross	0°30'	0°00'		0°11'
	Track differential angle	left				
		right				
	Toe	left	0°07'	0°00'	+/-0°06'	0°00'
		right	-0°02'			0°02'
		total	0°05'	0°00'	+/-0°12'	0°02'
	Setback			0°00'		
	Max steering lock	left steer	left	-38°30'	+/-2°00'	
			right	33°04'	+/-2°00'	
		right steer	left	33°04'	+/-2°00'	
			right	-38°30'	+/-2°00'	

Customer

Vehicle ident no.

Repair order no.
R002016Technician
61Date/Time
6.12.22 9:49License plate no.
SLG8769J

First reg. date

Model

TOYOTA ALTIS (ZRE171R)

Odometer reading: km/miles
408202

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left	-1°27'	-1°26' +/-0°30'	-1°27'
		right	-1°51'		-1°49'
		cross	0°24'	0°00' +/-0°30'	0°22'
	Toe	left	0°05'	0°06' +/-0°08'	0°07'
		right	0°00'		-0°02'
		total	0°05'	0°12' +/-0°16'	0°05'
	Geometrical driving axis		0°02'	0°00'	0°04'
Front axle	Camber	left	-2°23'	-0°35' +/-0°45'	-1°38'
		right	-0°52'		-0°44'
		cross	-1°31'	0°00' +/-0°30'	-0°55'
	Caster	left	3°25'	2°52' +/-0°45'	3°24'
		right	2°52'		2°50'
		cross	0°33'	0°00' +/-0°30'	0°34'
	SAI	left	13°04'	12°12'	12°59'
		right	12°56'		12°51'
		cross	0°08'	0°00'	0°09'
	Track differential angle	left			
		right			
	Toe	left	0°28'	0°00' +/-0°06'	0°03'
		right	0°10'		0°03'
		total	0°38'	0°00' +/-0°12'	0°06'
	Setback			0°00'	
	Max steering lock	left steer	left	-38°30' +/-2°00'	
			right	33°04' +/-2°00'	
		right steer	left	33°04' +/-2°00'	
			right	-38°30' +/-2°00'	

Vehicle Diagnostic Report

1ZRFE
408203 km

MR053REH104558000

Borneo Motors

Printed By: Default User(1)

13/12/2022 11:00:24 AM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT	Yes	P0420					-	30Z01000	No
	Yes	P1604	X		X			A0C01000	No
Cruise Control							-	-	No
ABS/VSC/TRC							-	F152602130	No
EMPS							-	8965B02220	No
Air Conditioner							-	8865002G1001	No
Combination Meter							-	83800F2K7001	No
								83800F2K7002	
Main Body							-	892211267002	No
D-Door Motor							-	-	No
SRS Airbag							-	8917F02380	No
Immobiliser							-	-	No

Vehicle Diagnostic Report

1ZRFE
408203 km

MR053REH104558000

Borneo Motors

Printed By: Default User(1)

13/12/2022 11:02:30 AM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT							-	30Z01000	No
								A0C01000	
Cruise Control							-	-	No
ABS/VSC/TRC							-	F152602130	No
EMPS							-	8965B02220	No
Air Conditioner							-	8865002G1001	No
Combination Meter							-	83800F2K7001	No
								83800F2K7002	
Main Body							-	892211267002	No
D-Door Motor							-	-	No
SRS Airbag							-	8917F02380	No
Immobiliser							-	-	No