



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

|                         |                                                                                                            |                     |                          |                           |                |
|-------------------------|------------------------------------------------------------------------------------------------------------|---------------------|--------------------------|---------------------------|----------------|
| <b>Customer</b>         | : INDIA INTERNATIONAL INSURANCE PTE<br>64 CECIL STREET<br>#04-00 & #05-00 IOB BUILDING<br>SINGAPORE 049711 | <b>Document No.</b> | : SQT22003557            | <b>Page</b>               | 1              |
| <b>Registration No</b>  | : SMA365M                                                                                                  | <b>Date</b>         | : 1. Dec 2022            | <b>Customer No.</b>       | : WZI007       |
| <b>Chassis No</b>       | : MRHFC5650JT000592                                                                                        | <b>Svc Advisor</b>  | : ANIKKA LAI SWEE KAM    | <b>Engine No</b>          | : R16B25500638 |
| <b>Model</b>            | : CIVIC 1.6 VTI YM2018                                                                                     | <b>Date   Time</b>  | : 1. Dec 2022 5:34:02 PM | <b>Surveyor Name</b>      | :              |
| <b>Owner's Name</b>     | : TAN JUI HONG                                                                                             | <b>Survey Date</b>  | :                        | <b>Authorisation Date</b> | :              |
| <b>Ins Policy No.</b>   | :                                                                                                          |                     |                          |                           |                |
| <b>Date of Accident</b> | : 30/11/2022                                                                                               |                     |                          |                           |                |

| Item            | Description                                                                                                                                                                            | Qty | Unit Price | Disc % | Amount | 7% GST Amount | Amount incld GST |
|-----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|--------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: TAN JUI HONG<br>OWNER INSURER: TOKIO MARINE<br>ACC DATE: 30/11/2022<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: III<br>TP VEH: GBJ1037L |     |            |        |        |               |                  |
| 60100-TEA-T00ZZ | HOOD COMPENGINE                                                                                                                                                                        | 1   | 691.00     | 25     | 518.25 | 36.28         | 554.53           |
| 60120-TEA-T00ZZ | HINGE COMPR.HOOD                                                                                                                                                                       | 1   | 38.10      | 25     | 28.57  | 2.00          | 30.57            |
| 74141-TEA-T00   | INSULATORHOOD                                                                                                                                                                          | 1   | 88.80      | 25     | 66.60  | 4.66          | 71.26            |
| 71101-TEA-T00ZZ | FACEFR.BUMPER                                                                                                                                                                          | 1   | 579.90     | 25     | 434.92 | 30.44         | 465.36           |
| 71193-TEA-T01   | SPACERR.FR.BUMPER SIDE                                                                                                                                                                 | 1   | 10.40      | 25     | 7.80   | 0.55          | 8.35             |
| 91505-TM8-003   | CLIP,BUMPER                                                                                                                                                                            | 10  | 2.30       | 25     | 17.25  | 1.21          | 18.46            |
| 33100-TEC-Q01   | HEADLIGHT ASSY,R.                                                                                                                                                                      | 1   | 675.90     | 25     | 506.92 | 35.48         | 542.40           |
| 34300-TET-H01   | LIGHT ASSYR.SIDE TURN                                                                                                                                                                  | 1   | 67.50      | 25     | 50.62  | 3.54          | 54.16            |
| 76208-TEA-T02   | MIRROR ASSY,R.                                                                                                                                                                         | 1   | 293.50     | 25     | 220.12 | 15.41         | 235.53           |
| 76201-TBA-A11ZN | CAP,R.SKULL                                                                                                                                                                            | 1   | 59.90      | 25     | 44.92  | 3.14          | 48.06            |
| 60211-TBA-A00ZZ | PANELR.FENDER                                                                                                                                                                          | 1   | 450.80     | 25     | 338.10 | 23.67         | 361.77           |
| 60213-TBA-A00ZZ | BRACKET AR.FR.FENDER                                                                                                                                                                   | 1   | 34.00      | 25     | 25.50  | 1.79          | 27.29            |
| 74101-TEA-T00   | FENDERR.FR.INNER                                                                                                                                                                       | 1   | 58.90      | 25     | 44.17  | 3.09          | 47.26            |
| 74285-TEA-T00   | PADR.FR.FENDER PARTITION                                                                                                                                                               | 1   | 50.90      | 25     | 38.17  | 2.67          | 40.84            |
| 67010-TEA-T00ZZ | PANEL COMPR.FR.DOOR                                                                                                                                                                    | 1   | 905.10     | 25     | 678.82 | 47.52         | 726.34           |
| 67410-T2M-T02ZZ | HINGER.FR.DOOR UPPER                                                                                                                                                                   | 1   | 44.30      | 25     | 33.22  | 2.33          | 35.55            |
| 67420-T2M-T02ZZ | HINGER.FR.DOOR LOWER                                                                                                                                                                   | 1   | 45.30      | 25     | 33.97  | 2.38          | 36.35            |
| 72340-TEA-T01   | CHECKER COMPFR.DOOR                                                                                                                                                                    | 1   | 15.60      | 25     | 11.70  | 0.82          | 12.52            |
| 72310-TEA-T01   | WEATHERSTRIPR.FR.DOOR                                                                                                                                                                  | 1   | 74.90      | 25     | 56.17  | 3.93          | 60.10            |

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer** : INDIA INTERNATIONAL INSURANCE PTE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711

**Registration No** : SMA365M

**Chassis No** : MRHFC5650JT000592

**Model** : CIVIC 1.6 VTI YM2018

**Owner's Name** : TAN JUI HONG

**Ins Policy No.** :

**Date of Accident** : 30/11/2022

**Document No.** : SQT22003557 **Page** 2

**Date** : 1. Dec 2022

**Customer No.** : WZI007

**Svc Advisor** : ANIKKA LAI SWEE KAM

**Engine No** : R16B25500638

**Date | Time** : 1. Dec 2022 5:34:02 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

| Item            | Description                         | Qty | Unit Price | Disc % | Amount | 7% GST Amount | Amount incld GST |
|-----------------|-------------------------------------|-----|------------|--------|--------|---------------|------------------|
| 72328-TEA-T01   | SEALR.FR.DOOR LOWER                 | 1   | 9.50       | 25     | 7.12   | 0.50          | 7.62             |
| 72336-TEA-T01   | SEALR.FR.DOOR FR.GAP                | 1   | 14.50      | 25     | 10.87  | 0.76          | 11.63            |
| 72410-TEA-T01   | MOLDING ASSYR.FR.DOOR               | 1   | 27.70      | 25     | 20.77  | 1.45          | 22.22            |
| 72142-TBA-A71   | BASE COMPR.FR.                      | 1   | 23.90      | 25     | 17.92  | 1.25          | 19.17            |
| 72141-TEA-T71ZP | HANDLE COMPR.                       | 1   | 98.60      | 25     | 73.95  | 5.18          | 79.13            |
| 72210-TEA-T01   | REGULATOR ASSYR.FR.DOOR             | 1   | 104.20     | 25     | 78.15  | 5.47          | 83.62            |
| 72231-TBA-A01   | SASHR.FR.DOOR CENTER LOWER          | 1   | 9.50       | 25     | 7.12   | 0.50          | 7.62             |
| 72235-TEA-T02   | RUNCHANNEL,R.FR.DOOR                | 1   | 79.90      | 25     | 59.92  | 4.19          | 64.11            |
| 67510-TEA-T00ZZ | PANELR.RR.DOOR                      | 1   | 828.00     | 25     | 621.00 | 43.47         | 664.47           |
| 67910-T2M-T02ZZ | HINGER.RR.DOOR UPPER                | 1   | 43.80      | 25     | 32.85  | 2.30          | 35.15            |
| 67920-T2M-T02ZZ | HINGER.RR.DOOR LOWER                | 1   | 44.30      | 25     | 33.22  | 2.33          | 35.55            |
| 72840-TEA-T01   | CHECKER COMPRR.DOOR                 | 1   | 10.90      | 25     | 8.17   | 0.57          | 8.74             |
| 72810-TEA-T01   | WEATHERSTRIP,R.RR.DOOR              | 1   | 95.30      | 25     | 71.47  | 5.00          | 76.47            |
| 72828-TEA-T01   | SEALRR.DOOR LOWER                   | 1   | 7.10       | 25     | 5.32   | 0.37          | 5.69             |
| 72910-TEA-T01   | MOLDING ASSYR.RR.DOOR               | 1   | 29.10      | 25     | 21.82  | 1.53          | 23.35            |
| 72710-TEA-T01   | REGULATOR ASSYR.RR.DOOR POWER       | 1   | 126.80     | 25     | 95.10  | 6.66          | 101.76           |
| 72731-TEA-T01   | SASHR.RR.DOOR RR.LOWER              | 1   | 14.40      | 25     | 10.80  | 0.76          | 11.56            |
| 72735-TEA-T02   | RUN CHANNEL,R.RR.DOOR               | 1   | 74.20      | 25     | 55.65  | 3.90          | 59.55            |
| 71800-TEA-T01ZB | GARNISH ASSY,R.SIDE SILL            | 1   | 135.90     | 25     | 101.92 | 7.13          | 109.05           |
| 04635-TEA-T00ZZ | PANELR.FR.OUTSIDE                   | 1   | 821.40     | 25     | 616.05 | 43.12         | 659.17           |
| 63322-TEA-T00ZZ | ADAPTERR.RR.COMBINATION LIGHT       | 1   | 70.00      | 25     | 52.50  | 3.68          | 56.18            |
| 66100-TEC-307ZZ | PANEL SETRR.                        | 1   | 280.70     | 25     | 210.52 | 14.74         | 225.26           |
| 66114-TBA-A00ZZ | STIFFENER,R.RR.PANEL SIDE           | 1   | 30.80      | 25     | 23.10  | 1.62          | 24.72            |
| 64301-TEA-T00ZZ | PANELR.RR.INSIDE                    | 1   | 244.70     | 25     | 183.52 | 12.85         | 196.37           |
| 64310-TEA-315ZZ | STIFFENER COMP.,R.RR.SHOCK ABSORBER | 1   | 150.00     | 25     | 112.50 | 7.88          | 120.38           |
| 64320-TEA-305ZZ | EXTSN COMPR.RR.W/ARCH RFCMNT        | 1   | 42.80      | 25     | 32.10  | 2.25          | 34.35            |
| 64330-TEC-U10ZZ | WHEELHOUSE COMPR.RR                 | 1   | 295.80     | 25     | 221.85 | 15.53         | 237.38           |
| 64350-TEA-T00ZZ | SUPPORT COMPR.RR.SHELF              | 1   | 56.30      | 25     | 42.22  | 2.96          | 45.18            |
| 65610-TEA-T11ZZ | FRAME COMP,R.RR.FLOOR               | 1   | 742.80     | 25     | 557.10 | 39.00         | 596.10           |

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer** : INDIA INTERNATIONAL INSURANCE PTE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711  
**Registration No** : SMA365M  
**Chassis No** : MRHFC5650JT000592  
**Model** : CIVIC 1.6 VTI YM2018  
**Owner's Name** : TAN JUI HONG  
**Ins Policy No.** :  
**Date of Accident** : 30/11/2022

**Document No.** : SQT22003557 **Page** 3  
**Date** : 1. Dec 2022  
**Customer No.** : WZI007  
**Svc Advisor** : ANIKKA LAI SWEE KAM  
**Engine No** : R16B25500638  
**Date | Time** : 1. Dec 2022 5:34:02 PM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

| Item            | Description               | Qty | Unit Price | Disc % | Amount | 7% GST Amount | Amount incld GST |
|-----------------|---------------------------|-----|------------|--------|--------|---------------|------------------|
| 33500-TEA-T01   | TAILLIGHT ASSYR.          | 1   | 301.70     | 25     | 226.27 | 15.84         | 242.11           |
| 33550-TEA-T01   | TAILLIGHT ASSYL.          | 1   | 324.70     | 25     | 243.52 | 17.05         | 260.57           |
| 34150-TEX-Y01   | LIGHT ASSYR.LID           | 1   | 141.10     | 25     | 105.82 | 7.41          | 113.23           |
| 34155-TEX-Y01   | LIGHT ASSYL.LID           | 1   | 141.10     | 25     | 105.82 | 7.41          | 113.23           |
| 68500-TEA-305ZZ | LID COMP,TRUNK            | 1   | 724.70     | 25     | 543.52 | 38.05         | 581.57           |
| 68610-TEA-T10ZZ | HINGE COMPR.TRUNK         | 1   | 51.60      | 25     | 38.70  | 2.71          | 41.41            |
| 68660-TEA-T10ZZ | HINGE COMPL.TRUNK         | 1   | 51.60      | 25     | 38.70  | 2.71          | 41.41            |
| 74895-TEX-Y01   | GARNISH ASSYR.TRUNK HINGE | 1   | 17.80      | 25     | 13.35  | 0.93          | 14.28            |
| 74851-TEA-003   | LOCK ASSYTRUNK            | 1   | 85.80      | 25     | 64.35  | 4.50          | 68.85            |
| 74865-TEA-T01   | WEATHERSTRIPTRUNK LID     | 1   | 70.00      | 25     | 52.50  | 3.68          | 56.18            |
| 74890-TEA-T11ZB | GARNISH ASSYRR.LICENSE    | 1   | 116.10     | 25     | 87.07  | 6.09          | 93.16            |
| 75701-TBA-A10   | EMBLEM,H-MARK             | 1   | 14.10      | 25     | 10.57  | 0.74          | 11.31            |
| 90301-ST0-003   | NUT,PUSH 3MM              | 2   | 2.10       | 25     | 3.15   | 0.22          | 3.37             |
| 75722-TBA-A00   | EMBLEM SETRR.             | 1   | 13.60      | 25     | 10.20  | 0.71          | 10.91            |
| 75725-TEA-T01   | EMBLEMRR.                 | 1   | 12.70      | 25     | 9.52   | 0.67          | 10.19            |
| 84601-TEA-Q02ZA | LINING ASSY,R.TRUNK       | 1   | 56.30      | 25     | 42.22  | 2.96          | 45.18            |
| 71500-TEC-Q00ZZ | FACE ASSY,RR.BUMPER       | 1   | 617.20     | 25     | 462.90 | 32.40         | 495.30           |
| 71593-TEA-T01   | SPACERR.RR.BUMPER SIDE    | 1   | 11.50      | 25     | 8.62   | 0.60          | 9.22             |
| 71598-TEA-T01   | SPACERL.RR.BUMPER SIDE    | 1   | 11.50      | 25     | 8.62   | 0.60          | 9.22             |
| 91505-TM8-003   | CLIP,BUMPER               | 10  | 2.30       | 25     | 17.25  | 1.21          | 18.46            |
| 71503-TEA-T00   | GARNISH,R.RR.BUMPER SIDE  | 1   | 9.00       | 25     | 6.75   | 0.47          | 7.22             |
| 71504-TBA-A00   | COVERR.FINISHER           | 1   | 13.00      | 25     | 9.75   | 0.68          | 10.43            |
| 33505-TEA-T01   | REFLECTOR ASSYR.RR.       | 1   | 19.20      | 25     | 14.40  | 1.01          | 15.41            |
| 71502-TEX-Y00   | GARNISH,RR.BUMPER LOWER   | 1   | 42.00      | 25     | 31.50  | 2.21          | 33.71            |
| 71530-TEA-T00ZZ | BEAM COMPRR.BUMPER        | 1   | 190.10     | 25     | 142.57 | 9.98          | 152.55           |
| 42700-TEA-T61   | DISKALUMINIUM WHEEL       | 1   | 480.00     | 25     | 360.00 | 25.20         | 385.20           |
| 73227-TEA-003   | RUBBER CWINDOWSHIELD DAM  | 1   | 19.90      | 25     | 14.92  | 1.04          | 15.96            |
| 73525-SYY-000   | RUBBERRR QTR W/SHIELD     | 3   | 10.40      | 25     | 23.40  | 1.64          | 25.04            |
| 91501-S70-003   | FASTENER BW/SHIELD        | 2   | 5.30       | 25     | 7.95   | 0.56          | 8.51             |

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

|                  |                                                                                                            |                    |                          |      |   |
|------------------|------------------------------------------------------------------------------------------------------------|--------------------|--------------------------|------|---|
| Customer         | : INDIA INTERNATIONAL INSURANCE PTE<br>64 CECIL STREET<br>#04-00 & #05-00 IOB BUILDING<br>SINGAPORE 049711 | Document No.       | : SQT22003557            | Page | 4 |
| Registration No  | : SMA365M                                                                                                  | Date               | : 1. Dec 2022            |      |   |
| Chassis No       | : MRHFC5650JT000592                                                                                        | Customer No.       | : WZI007                 |      |   |
| Model            | : CIVIC 1.6 VTI YM2018                                                                                     | Svc Advisor        | : ANIKKA LAI SWEE KAM    |      |   |
| Owner's Name     | : TAN JUI HONG                                                                                             | Engine No          | : R16B25500638           |      |   |
| Ins Policy No.   | :                                                                                                          | Date   Time        | : 1. Dec 2022 5:34:02 PM |      |   |
| Date of Accident | : 30/11/2022                                                                                               | Surveyor Name      | :                        |      |   |
|                  |                                                                                                            | Survey Date        | :                        |      |   |
|                  |                                                                                                            | Authorisation Date | :                        |      |   |

| Item              | Description                                    | Qty | Unit Price | Disc % | Amount         | 7% GST Amount | Amount incld GST |
|-------------------|------------------------------------------------|-----|------------|--------|----------------|---------------|------------------|
| 91536-SS0-J01     | FASTENER AW/SHIELD                             | 2   | 3.80       | 25     | 5.70           | 0.40          | 6.10             |
| 91568-TF0-003     | CLIP,WINDSHIELD UPPER                          | 2   | 3.50       | 25     | 5.25           | 0.37          | 5.62             |
| 73125-SR3-000     | RUBBER, W/SHIELD                               | 1   | 14.20      | 25     | 10.65          | 0.75          | 11.40            |
| 73126-SR3-000     | RUBBER, W/SHIELD                               | 1   | 16.20      | 25     | 12.15          | 0.85          | 13.00            |
| BO-WS-SEALANT     | WINDSCREEN SEALANT (N)                         | 2   | 60.00      |        | 120.00         | 8.40          | 128.40           |
| 73500-TEA-T02     | GLASS ASSYR.QUARTER WINDSHIELD                 | 1   | 157.50     | 25     | 118.12         | 8.27          | 126.39           |
| Sum Item          |                                                |     |            |        | <b>9516.17</b> | <b>666.18</b> | <b>10,182.35</b> |
| BO-WHEEL ALIGN X4 | WHEEL ALIGNMENT X4                             | 1   | 180.00     |        | 180.00         | 12.60         | 192.60           |
| BO-R-COOL-RRQ     | SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS. | 1   | 250.00     |        | 250.00         | 17.50         | 267.50           |
| Sum Ext. Service  |                                                |     |            |        | <b>430.00</b>  | <b>30.10</b>  | <b>460.10</b>    |
| BOSUN             | SUNDRIES                                       | 1   | 100.00     |        | 100.00         | 7.00          | 107.00           |
| BML01I            | INSPECT FR LIGHTING MECHANISMS & FOCUS         | 1   | 180.00     |        | 180.00         | 12.60         | 192.60           |
| BML02I            | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER  | 1   | 180.00     |        | 180.00         | 12.60         | 192.60           |
| BA02R             | REMOVE & RENEW REVERSE SENSORS-4 PCS (N)       | 1   | 180.00     |        | 180.00         | 12.60         | 192.60           |
| BMI03D            | REMOVE & INSTALL REAR COMPARTMENT LININGS      | 1   | 650.00     |        | 650.00         | 45.50         | 695.50           |
| BKTRR             | REMOVE & TRANSFER ITEMS TO NEW TRUNK LID       | 1   | 450.00     |        | 450.00         | 31.50         | 481.50           |
| BKDR12R           | REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST | 1   | 450.00     |        | 450.00         | 31.50         | 481.50           |
| BKDR22R           | REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST | 1   | 450.00     |        | 450.00         | 31.50         | 481.50           |
| BC012R            | RESET VEHICLE SMART ENTRY SYSTEM               | 1   | 450.00     |        | 450.00         | 31.50         | 481.50           |
| BC011R            | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA    | 1   | 450.00     |        | 450.00         | 31.50         | 481.50           |
| BG02R             | REPLACE RR. WINDSCREEN.(N)                     | 1   | 650.00     |        | 650.00         | 45.50         | 695.50           |
| BG52R             | REPLACE RR. R QTR GLASS.(N)                    | 1   | 650.00     |        | 650.00         | 45.50         | 695.50           |
| BOJSE             | BODY JOINT SEALANT RHR FENDER                  | 1   | 100.00     |        | 100.00         | 7.00          | 107.00           |
| BOJSE             | BODY JOINT SEALANT RHR QTR GLASS               | 1   | 100.00     |        | 100.00         | 7.00          | 107.00           |
| BOJSE             | BODY JOINT SEALANT TAILGATE                    | 1   | 100.00     |        | 100.00         | 7.00          | 107.00           |

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer** : INDIA INTERNATIONAL INSURANCE PTE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711  
**Registration No** : SMA365M  
**Chassis No** : MRHFC5650JT000592  
**Model** : CIVIC 1.6 VTI YM2018  
**Owner's Name** : TAN JUI HONG  
**Ins Policy No.** :  
**Date of Accident** : 30/11/2022

**Document No.** : SQT22003557 **Page** 5  
**Date** : 1. Dec 2022  
**Customer No.** : WZI007  
**Svc Advisor** : ANIKKA LAI SWEE KAM  
**Engine No** : R16B25500638  
**Date | Time** : 1. Dec 2022 5:34:02 PM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

| Item      | Description                                         | Qty | Unit Price | Disc % | Amount   | 7% GST Amount | Amount incld GST |
|-----------|-----------------------------------------------------|-----|------------|--------|----------|---------------|------------------|
| BOJSE     | BODY JOINT SEALANT END PANEL                        | 1   | 100.00     |        | 100.00   | 7.00          | 107.00           |
| BKFE22R   | CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL     | 1   | 8000.00    |        | 8000.00  | 560.00        | 8560.00          |
| BP08R     | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (13P) | 1   | 7500.00    |        | 7500.00  | 525.00        | 8025.00          |
| Sum Labor |                                                     |     |            |        | 20740.00 | 1,451.80      | 22,191.80        |

Survey By

Date & Time

Excess

Status

Signature

**Total Amount** 30,686.17 2,148.08 32,834.25

**Total (Inclusive of GST)** 32,834.25

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co, Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.