



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA365M
Chassis No : MRHFC5650JT000592
Model : CIVIC 1.6 VTI YM2018
Owner's Name : TAN JUI HONG
Ins Policy No :
Date of Accident : 30/11/2022

Document No. : SQT22003557 Page 1
Date : 1. Dec 2022
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25500638
Date | Time : 1. Dec 2022 5:34:02 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN JUI HONG OWNER INSURER: TOKIO MARINE ACC DATE: 30/11/2022 SURVEYED BY: DATE: REF NO: TP INSURER: III TP VEH: GBJ1037L						
60100-TEA-T00ZZ	HOOD COMPENGINE	1	691.00	25	518.25	36.28	554.53
60120-TEA-T00ZZ	HINGE COMPR.HOOD	1	38.10	25	28.57	2.00	30.57
74141-TEA-T00	INSULATORHOOD	1	88.80	25	66.60	4.66	71.26
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
33100-TEC-Q01	HEADLIGHT ASSY,R.	1	675.90	25	506.92	35.48	542.40
34300-TET-H01	LIGHT ASSYR.SIDE TURN	1	67.50	25	50.62	3.54	54.16
76208-TEA-T02	MIRROR ASSY,R.	1	293.50	25	220.12	15.41	235.53
76201-TBA-A11ZN	CAP,R.SKULL	1	59.90	25	44.92	3.14	48.06
60211-TBA-A00ZZ	PANELR.FENDER	1	450.80	25	338.10	23.67	361.77
60213-TBA-A00ZZ	BRACKET AR.FR.FENDER	1	34.00	25	25.50	1.79	27.29
74101-TEA-T00	FENDERR.FR INNER	1	58.90	25	44.17	3.09	47.26
74285-TEA-T00	PADR.FR.FENDER PARTITION	1	50.90	25	38.17	2.67	40.84
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR	1	905.10	25	678.82	47.52	726.34
67410-T2M-T02ZZ	HINGER.FR.DOOR UPPER	1	44.30	25	33.22	2.33	35.55
67420-T2M-T02ZZ	HINGER.FR.DOOR LOWER	1	45.30	25	33.97	2.38	36.35
72340-TEA-T01	CHECKER COMPFR.DOOR	1	15.60	25	11.70	0.82	12.52
72310-TEA-T01	WEATHERSTRIPR.FR.DOOR	1	74.90	25	56.17	3.93	60.10

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA365M
Chassis No : MRHFC5650JT000592
Model : CIVIC 1.6 VTI YM2018
Owner's Name : TAN JUI HONG
Ins Policy No. :
Date of Accident : 30/11/2022

Document No. : SQT22003557 Page 2
Date : 1. Dec 2022
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25500638
Date | Time : 1. Dec 2022 5:34:02 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST	
72328-TEA-T01	SEALR.FR.DOOR LOWER	1	9.50	25	7.12	0.50	7.62	NEC
72336-TEA-T01	SEALR.FR.DOOR FR.GAP	1	14.50	25	10.87	0.76	11.63	NN
72410-TEA-T01	MOLDING ASSYR.FR.DOOR	1	27.70	25	20.77	1.45	22.22	
72142-TBA-A71	BASE COMPR.FR.	1	23.90	25	17.92	1.25	19.17	
72141-TEA-T71ZP	HANDLE COMPR.	1	98.60	25	73.95	5.18	79.13	
72210-TEA-T01	REGULATOR ASSYR.FR.DOOR	1	104.20	25	78.15	5.47	83.62	SVC
72231-TBA-A01	SASHR.FR.DOOR CENTER LOWER	1	9.50	25	7.12	0.50	7.62	NN
72235-TEA-T02	RUNCHANNEL,R.FR.DOOR	1	79.90	25	59.92	4.19	64.11	NN
67510-TEA-T00ZZ	PANELR.RR.DOOR	1	828.00	25	621.00	43.47	664.47	
67910-T2M-T02ZZ	HINGER.RR.DOOR UPPER	1	43.80	25	32.85	2.30	35.15	BT
67920-T2M-T02ZZ	HINGER.RR.DOOR LOWER	1	44.30	25	33.22	2.33	35.55	NN
72840-TEA-T01	CHECKER COMPRR.DOOR	1	10.90	25	8.17	0.57	8.74	NN
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR	1	95.30	25	71.47	5.00	76.47	DD
72828-TEA-T01	SEALRR.DOOR LOWER	1	7.10	25	5.32	0.37	5.69	NEC
72910-TEA-T01	MOLDING ASSYR.RR.DOOR	1	29.10	25	21.82	1.53	23.35	
72710-TEA-T01	REGULATOR ASSYR.RR.DOOR POWER	1	126.80	25	95.10	6.66	101.76	NN
72731-TEA-T01	SASHR.RR.DOOR RR.LOWER	1	14.40	25	10.80	0.76	11.56	NN
72735-TEA-T02	RUN CHANNEL,R.RR.DOOR	1	74.20	25	55.65	3.90	59.55	NN
71800-TEA-T01ZB	GARNISH ASSY,R.SIDE SILL	1	135.90	25	101.92	7.13	109.05	
04635-TEA-T00ZZ	PANELR.FR.OUTSIDE	1	821.40	25	616.05	43.12	659.17	
63322-TEA-T00ZZ	ADAPTERR.RR.COMBINATION LIGHT	1	70.00	25	52.50	3.68	56.18	NEC
66100-TEC-307ZZ	PANEL SETRR. <i>pluto</i>	1	280.70	25	210.52	14.74	225.26	
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	30.80	25	23.10	1.62	24.72	NEC
64301-TEA-T00ZZ	PANELR.RR.INSIDE	1	244.70	25	183.52	12.85	196.37	NEC
64310-TEA-315ZZ	STIFFENER COMP.,R.RR.SHOCK ABSORBER	1	150.00	25	112.50	7.88	120.38	SVC
64320-TEA-305ZZ	EXTSN COMPR.RR.W/ARCH RFCMNT	1	42.80	25	32.10	2.25	34.35	SVC
64330-TEC-U10ZZ	WHEELHOUSE COMPR.RR	1	295.80	25	221.85	15.53	237.38	R
64350-TEA-T00ZZ	SUPPORT COMPR.RR.SHELF	1	56.30	25	42.22	2.96	45.18	R
65610-TEA-T11ZZ	FRAME COMP,R.RR.FLOOR	1	742.80	25	557.10	39.00	596.10	R

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA365M
Chassis No : MRHFC5650JT000592
Model : CIVIC 1.6 VTI YM2018
Owner's Name : TAN JUI HONG
Ins Policy No :
Date of Accident : 30/11/2022

Document No. : SQT22003557
Date : 1. Dec 2022
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25500638
Date | Time : 1. Dec 2022 5:34:02 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
33500-TEA-T01	TAILLIGHT ASSYR.	1	301.70	25	226.27	15.84	242.11
33550-TEA-T01	TAILLIGHT ASSYL.	1	324.70	25	243.52	17.05	260.57
34150-TEX-Y01	LIGHT ASSYR.LID	1	141.10	25	105.82	7.41	113.23
34155-TEX-Y01	LIGHT ASSYL.LID	1	141.10	25	105.82	7.41	113.23
68500-TEA-305ZZ	LID COMP.TRUNK	1	724.70	25	543.52	38.05	581.57
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	51.60	25	38.70	2.71	41.41
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	51.60	25	38.70	2.71	41.41
74895-TEX-Y01	GARNISH ASSYR.TRUNK HINGE	1	17.80	25	13.35	0.93	14.28
74851-TEA-003	LOCK ASSYTRUNK	1	85.80	25	64.35	4.50	68.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	116.10	25	87.07	6.09	93.16
75701-TBA-A10	EMBLEM,H-MARK	1	14.10	25	10.57	0.74	11.31
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.22	3.37
75722-TBA-A00	EMBLEM SETRR.	1	13.60	25	10.20	0.71	10.91
75725-TEA-T01	EMBLEMRR.	1	12.70	25	9.52	0.67	10.19
84601-TEA-Q02ZA	LINING ASSY,R.TRUNK	1	56.30	25	42.22	2.96	45.18
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	1	9.00	25	6.75	0.47	7.22
71504-TBA-A00	COVERR.FINISHER	1	13.00	25	9.75	0.68	10.43
33505-TEA-T01	REFLECTOR ASSYR.RR.	1	19.20	25	14.40	1.01	15.41
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	42.00	25	31.50	2.21	33.71
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	190.10	25	142.57	9.98	152.55
42700-TEA-T61	DISKALUMINIUM WHEEL	1	480.00	25	360.00	25.20	385.20
73227-TEA-003	RUBBER CWINDOWSHIELD DAM	1	19.90	25	14.92	1.04	15.96
73525-SYY-000	RUBBERRR QTR W/SHIELD	3	10.40	25	23.40	1.64	25.04
91501-S70-003	FASTENER BW/SHIELD	2	5.30	25	7.95	0.56	8.51

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA365M
Chassis No : MRHFC5650JT000592
Model : CIVIC 1.6 VTI YM2018
Owner's Name : TAN JUI HONG
Ins Policy No. :
Date of Accident : 30/11/2022

Document No. : SQT22003557 **Page** 4
Date : 1. Dec 2022
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25500638
Date | Time : 1. Dec 2022 5:34:02 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	3.50	25	5.25	0.37	5.62
73125-SR3-000	RUBBER, W/SHIELD	1	14.20	25	10.65	0.75	11.40
73126-SR3-000	RUBBER, W/SHIELD	1	16.20	25	12.15	0.85	13.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
73500-TEA-T02	GLASS ASSYR.QUARTER WINDSHIELD	1	157.50	25	118.12	8.27	126.39
Sum Item					9516.17	666.18	10,182.35
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00		250.00	17.50	267.50
Sum Ext. Service					430.00	30.10	460.10
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	450.00		450.00	31.50	481.50
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	450.00		450.00	31.50	481.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	450.00		450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	31.50	481.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1	650.00		650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT RHR FENDER	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT RHR QTR GLASS	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00		100.00	7.00	107.00

Printed on 1/12/2022 6:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA365M
Chassis No : MRHFC5650JT000592
Model : CIVIC 1.6 VTI YM2018
Owner's Name : TAN JUI HONG
Ins Policy No. :
Date of Accident : 30/11/2022

Document No. : SQT22003557 Page 5
Date : 1. Dec 2022
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B25500638
Date | Time : 1. Dec 2022 5:34:02 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00		100.00	7.00	107.00
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	8000.00		8000.00	560.00	8560.00
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (13P)	1	7500.00		7500.00	525.00	8025.00
BO-TOW	TOWING SERVICES (MBBS)	1	100.00		100.00	7.00	107.00
Sum Labor					20840.00	1,458.80	22,298.80

Survey By : Tan Jui Hong 97495749 / 62563561
Date & Time : 05/12/22 @ 2pm
Excess : WP
Status :
Signature : [Signature]

Total Amount 30,786.17 2,155.08 32,941.25
Total (Inclusive of GST) 32,941.25

Resurvey before paint
16-17 days
tan jui hong e/kuauto.com.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Printed on 1/12/2022 6:49:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0052789 / TAN JUI HONG

Chassis No: MRHFC5650JT000592

License No: SMA365M

Mileage: 44652

Engine No: R16B25500638

Document No: SVO22053747

Printed By: ANIKKALAI

Order Date: 5. December 2022

Order Time: 4:51:13 PM

Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
80050-TG7-000	LABEL AIR CON	1	0.80	25	0.60	0.04	0.64 /
19043-5AA-E00	LABEL, COOLANT INFORMATION	1	11.50	25	8.62	0.60	9.22 /
90682-SEA-003	CLIP ABUMPER	2	2.60	25	3.90	0.27	4.17 /
91626-STK-A01	GROMMET TAILLIGHT	2	0.40	25	0.60	0.04	0.64 /
90667-SWZ-003ZV	CLIP, TRIM, 7MM NH900L	2	3.10	25	4.65	0.33	4.98 /
90667-TC0-U01ZM	CLIP ASSY,TRIM	2	2.50	25	3.75	0.26	4.01 /
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.50	25	1.87	0.13	2.00 /
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	32.40	25	24.30	1.70	26.00 /
63321-TEA-T00ZZ	GUTTERR.RR.UPPER	1	34.00	25	25.50	1.79	27.29 /
75450-TEA-T02	OUTLET ASSY,RR.AIR	1	9.40	25	7.05	0.49	7.54 /
72425-TBA-A01	MOLDING ASSYR.FR.DOOR SASH	1	30.60	25	22.95	1.61	24.56 /
72430-TEA-T01	GARNISH ASSYR.FR.DOOR SASH	1	15.80	25	11.85	0.83	12.68 /
72456-TEA-T01	GARNISHR.FR.CENTER CORNER	1	1.80	25	1.35	0.09	1.44 /
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER	1	57.30	25	42.97	3.01	45.98 /
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH	1	28.30	25	21.22	1.49	22.71 /
72956-TEA-T01	GARNISHR.RR.CENTER CORNER	1	1.60	25	1.20	0.08	1.28 /
72110-TEA-T03	LATCH ASSY,R.FR.DOOR	1	106.30	25	79.72	5.58	85.30 /
72147-TEA-T01ZP	COVERR.FR.BASE	1	2.70	25	2.02	0.14	2.16 /
SUM PARTS:					264.12	18.48	282.60
TOTAL SGD					264.12	18.48	282.60

Total Payable (SGD)

282.60

GST Amount is calculated from individual line(s)