

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22012121/TNCE2**Date:** 04/05/2023**REFERENCE**

Insured/Claimant:	Ho Boon Kin, Mark	Policy No:	1900114789-02	
Date of Loss:	28/11/2022	Nature of Claim:	OD	Claim No: 1894525096SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB1752R		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK083064
Reg. Date:	28/06/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF50KA055465
Colour:	Grey	Odometer:	31220 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$154,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,137.00	7,436.96	9,700.04	56.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,732.00	6,102.00	7,630.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	30,869.00	13,538.96	17,330.04	56.14
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	29,269.00	11,938.96	17,330.04	59.21
+ GST 8.00/8.00% (\$\$)	2,341.52	955.12	1,386.40	59.21
Nett Amount (\$\$)	31,610.52	12,894.08	18,716.44	59.21

INSPECTION

Date of Assignment:	05/12/2022		
Date Inspected:	02/12/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Bent	3,977.00 FS	*3,181.60 FS
2	1		*FRONT OUTER DOOR SEAL-RH	Necessary	247.00 FS	*197.20 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*FRONT DOOR CATCH-RH	Bent	134.00 FS	*106.80 FS
7	1		*FRONT DOOR CHROME TRIM-RH	Cut	171.00 FS	*136.40 FS
8	1		*FRONT DOOR TYRE PRESSURE DATA PLATE	Necessary	41.00 FS	*33.36 FS
9	1		*FRONT DOOR HANDLE TRIM PLATE	Not Necessary	98.00 FS	*- FS
10	1		*FRONT DOOR HANDLE CHROME TRIM-RH	Not Necessary	152.00 FS	*- FS
11	1		*FRONT DOOR HANDLE COVER CAP-RH	Not Necessary	7.00 FS	*- FS
12	1		*FRONT DOOR MOUNTING BAR-RH	Not Necessary	183.00 FS	*- FS
13	1		*FRONT WINDOW REGULATOR-RH	Not Necessary	392.00 FS	*- FS
14	1		*REAR DOOR-RH	Bent	3,977.00 FS	*3,181.60 FS
15	1		*REAR OUTER DOOR SEAL-RH	Necessary	247.00 FS	*197.20 FS
16	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
18	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
19	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	135.00 FS	*- FS
20	1		*REAR DOOR CATCH-RH	Bent	134.00 FS	*106.80 FS
21	1		*SIDE MEMBER TRIM-RH	Repair	872.00 FS	*- FS
22	1		*SIDE MEMBER TRIM ATTACHMENT PARTS-RH	Necessary	136.00 FS	*108.80 FS
23	1		*ADHESIVE TAPES	Necessary	221.00 FS	*176.80 FS
24	1		*REAR DOOR SILL TRIM STRIP-RH	Not Necessary	133.00 FS	*- FS
25	1		*REAR BUMPER	Repair	3,012.00 FS	*- FS
26	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
27	1		*REAR BUMPER CHROME TRIM	Not Necessary	1,139.00 FS	*- FS
28	1		*REAR BUMPER GUIDE SECTION-RH UPPER	Not Necessary	26.00 FS	*- FS
29	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	49.00 FS	*- FS
30	1		*REAR WHEEL HOUSING LINER-RH	Not Necessary	299.00 FS	*- FS
31	1		*REAR DOOR HINGE HALF-RH LOWER	Not Necessary	85.00 FS	*- FS
32	1		*REAR DOOR HINGE HALVES-RH LOWER	Not Necessary	53.00 FS	*- FS
33	1		*REAR DOOR HINGE HALF-RH UPPER	Not Necessary	49.00 FS	*- FS
34	1		*REAR DOOR HINGE HALVES-RH LOWER	Not Necessary	51.00 FS	*- FS
35	1		*RHS REAR RIM (NPA)	Not Necessary	0.00 FS	*- FS
36	1		*SUNDRIES	Necessary	600.00 FS	*10.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **17,137.00** **7,436.96**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	800.00	800.00
3	TO DISMANTLE AND RENEW REAR BUMPER,RHS REAR DOOR,RHS FRONT DOOR AND RHS SILL PANEL TRIM.TO REPAIR RHS REAR FENDER,RHS SILL PANEL AND RHS B-PILLAR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,000.00	2,000.00
4	TO RESPRAY RHS FRONT DOOR,DOOR HANDLE,RHS REAR DOOR,HINGES,RHS SILL PANEL TRIM,RHS SILL PANEL,RHS B-PILLAR,DOOR ENTRANCES,RHS REAR FENDER AND REAR BUMPER	New	7,000.00	2,750.00
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	192.00
Gross Labour Cost (\$)			13,732.00	6,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >