



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/01076/2022/EQ
DATE	:	1-Dec-22
WIP	:	52725

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/12/2022

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MR HO BOON KIN, MARK
ADDRESS	:	28 WILBY ROAD #03-37 SINGAPORE 276309
TELEPHONE	:	HP +65 91549235
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900114789-02
VEHICLE NO	:	SKB 1752 R
MODEL CODE	:	AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR	:	28/6/2019
ENGINE NO	:	CVK 083064
CHASSIS NO	:	WAUZZZF50KA055465
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	28-Nov-22
PLACE OF ACCIDENT	:	BUKIT MERAH BLK 164-165 OPEN CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKB 1752 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	✓ ✓
3	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR, RHS FRONT DOOR AND RHS SILL PANEL TRIM. TO REPAIR RHS REAR FENDER, RHS SILL PANEL AND RHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,000.00	2000 ✓
4	TO RESPRAY RHS FRONT DOOR, DOOR HANDLE, RHS REAR DOOR, HINGES, RHS SILL PANEL TRIM, RHS SILL PANEL, RHS B-PILLAR, DOOR ENTRANCES, RHS REAR FENDER AND REAR BUMPER.	\$ 7,000.00	2750 ✓
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X X n n
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	✓ ✓ 192
TOTAL LABOUR CHARGES		: \$ 13,732.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 1752 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1 \$	3,977.00	bt 3181.6
2	FRONT OUTER DOOR SEAL - RH	1 \$	247.00	net 197.2
3	BONDING AGENT	1 \$	51.00	?x
4	CLEANING SOLUTION	1 \$	74.00	?x
5	APPLICATOR	1 \$	9.00	?x
6	FRONT DOOR CATCH - RH	1 \$	134.00	?x bt 106.8
7	FRONT DOOR CHROME TRIM - RH	1 \$	171.00	net 136.4
8	FRONT DOOR TYRE PRESSURE DATA PLATE	1 \$	41.00	net 33.36
9	FRONT DOOR HANDLE TRIM PLATE	1 \$	98.00	?x
10	FRONT DOOR HANDLE CHROME TRIM - RH	1 \$	152.00	?x
11	FRONT DOOR HANDLE COVER CAP - RH	1 \$	7.00	?x
12	FRONT DOOR MOUNTING BAR - RH	1 \$	183.00	?x
13	FRONT WINDOW REGULATOR - RH	1 \$	392.00	?x
14	REAR DOOR - RH	1 \$	3,977.00	bt 3181.6
15	REAR OUTER DOOR SEAL - RH	1 \$	247.00	net 197.2
16	BONDING AGENT	1 \$	51.00	?x
17	CLEANING SOLUTION	1 \$	74.00	?x
18	APPLICATOR	1 \$	9.00	?x
19	REAR DOOR ATTACHMENT PARTS	1 \$	135.00	?x
20	REAR DOOR CATCH - RH	1 \$	134.00	?x 106.8 bt
SUB TOTAL SPARE PARTS		:	\$ 10,163.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 1752 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	SIDE MEMBER TRIM - RH	1 \$	872.00	Ry
22	SIDE MEMBER TRIM ATTACHMENT PARTS - RH	1 \$	136.00	rec 108.8
23	ADHESIVE TAPES	1 \$	221.00	rec 176.8
24	REAR DOOR SILL TRIM STRIP - RH	1 \$	133.00	X x nn
25	REAR BUMPER	1 \$	3,012.00	Ry
26	REAR BUMPER SECURING STRIP	1 \$	249.00	X
27	REAR BUMPER CHROME TRIM	1 \$	1,139.00	X
28	REAR BUMPER GUIDE SECTION - RH UPPER	1 \$	26.00	X
29	REAR BUMPER GUIDE SECTION - RH	1 \$	49.00	X
30	REAR WHEEL HOUSING LINER - RH	1 \$	299.00	X
31	REAR DOOR HINGE HALVES - RH LOWER	1 \$	53.00	X ?
32	REAR DOOR HINGE HALF - RH LOWER	1 \$	85.00	X ?
33	REAR DOOR HINGE HALF - RH UPPER	1 \$	49.00	X ?
34	REAR DOOR HINGE HALVES - RH LOWER	1 \$	51.00	X ?
35	RHS REAR RIM	S/N	TBC	
36	SUNDRIES	\$	600.00	? 10.40 rec
TOTAL SPARE PARTS		:	\$ 17,137.00	
TOTAL LABOUR CHARGES		:	\$ 13,732.00	
GRAND TOTAL		:	\$ 30,869.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 9749544
Not Authorise Ex: to be advise
Resny before paint
taufik e lkkauto.com
7 days
02/12/22 e 245pm

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WIT
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: