

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS, \$ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

9/12/22
 SJT8206496071
 2022-04-2029 MA 516759
 1/5 * 3500 in hand AH long

Mark Harris Tony

NOT Authorised
 5/12/22
 2/ < \$3500
 4 days

VEHICLE NO **SJT 8206Y** VW GOLF

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>						
1	Rear bumper	DD / cm	1162.32	1270.00	—	
1	Rear bumper lower (skirt) cover	du / torn	305.40	980.00	—	
2	Rear bumper side retainers @110.00	11		220.00	X	
1	Rear bumper reinforcement	Buf	492.60	746.00	—	
1	Rear bumper inner foam	NE		110.00	X	
2	Rear bumper reflectors @ 122.50 60x20	cm	120	245.00	—	
2	Rear number plate lamp @78.00	11		156.00	X	
1	Rear end panel	11	681	782.00	—	
1	Rear end panel top garnish	11		382.00	X	
1	Rear tailgate	R		1752.00	X	
2	Rear tailgate reflectors \$274	11		548.00	X	
1	Rear windscreen	REFIX 11		0.00	X	
1	Rear tailgate wiper motor/blade	REFIX 11		0.00	X	
1	Rear tailgate inner trim board	11		278.00	X	
1	Rear tailgate outer handle VW	11		112.00	X	
1	Rear tailgate inner lock	11		278.00	X	
1	Rear tailgate inner lock catch	11		98.00	X	
1	Rear boot edge weatherstrip	twi		138.00	—	
2	Rear tailgate dampers	REFIX 11		0.00	X	
2	RHS & LHS Taillamps @ 624.30	11		1248.00	X	
				9343.00		
		less 10%	10%	934.30	10%	
				8408.70		
<u>SPECIAL NETT ITEMS</u>						
1 set	Reverse sensors	stunth		280.00	200	
1	Rear tailgate GOLF emblem	ner		98.00	40	
1	Rear tailgate GT emblem	ner		68.00	40	
1	Rear tailgate TSI emblem	ner		72.00	40	
1	Rear tailgate TRIPLE S sticker	ner		60.00	50	
1	Rear end panel sealant	11		100.00	X	
1	Rear windscreen sealant	11		100.00	X	
1set	Rear bumper clips	ner		60.00	40	
1set	Rear end panel top garnish clips	11		60.00	X	
1	Rear licence plate w/holder	11		75.00	X	
TOTAL PARTS				9381.70		

VEHICLE NO SJT 8206Y VW GOLF

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	900.00	700
3	To remove, refix wiring system at accident damaged areas and check for proper function	100.00	20
4	To remove and replace reverse sensors and check for proper function	100.00	50
5	To remove and refix rear windscreen	120.00	an X
6	To perform anti-rust treatment on affected areas	120.00	30
7	To clear fault code with diagnostic computer and reset to specification	250.00	an X
	Labour Total :	2790.00	
	TOTAL (PARTS & LABOUR):	12171.70	

PRELIMINARY ESTIMATE

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2899.32
 102
 2609.38
 410
 1400
 4419.38
 202
 3535