



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG		Ref: CC4/ASM22012132/Dpa3q2 Date: 21/02/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLC 9325X	Veh. Inspected	SJD 5867T
Policy No.	GA351195	Coverage (\$)	0.00
Claim No.	S2M04FW2	Excess (\$)	0.00
Assign From		Assign Date	05/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305050678	Colour	BLACK
Odometer	226186 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	DUNLOP	5 mm
L/H Front Tyre	185/60 R15	DUNLOP	5 mm
R/H Rear Tyre	185/60 R15	DUNLOP	5 mm
L/H Rear Tyre	185/60 R15	DUNLOP	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	01/12/2022	Inspection Date	07/12/2022
Survey held at	GOH LEE HWA AUTOMOBILE PTE LTD BLK.5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	