

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22012135/DYA3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKP8681S **Insured Vehicle No :** SNC2169C

Date of Loss: 30/11/2022 Nature of Claim: TP Claim No: MFL2022D0010832

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP8681S**
 Make & Model: MERCEDES-BENZ C180K, 1.6 (A) Engine No: 27191031301064
 Reg. Date: 01/02/2010 (Man. Year: 2009) Chassis No: WDD2040452A356145
 Colour: White Odometer: 160263 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
 Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,905.10	0.00	47,905.10	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,840.00	500.00	8,340.00	94.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	56,745.10	500.00	56,245.10	99.12
+ GST 8.00/8.00% (S\$)	4,539.61	40.00	4,499.61	99.12
Nett Amount (S\$)	61,284.71	540.00	60,744.71	99.12
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		1,477.25		

INSPECTION

Date of Assignment: 05/12/2022

Date Inspected: 06/12/2022 Inspected At:

C. S. Ong Auto Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A,
#03-08 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2023)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP8681S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	2,127.00 FL	*- FL
2	1		*BOOTLID LOGO	Not Necessary	74.00 FL	*- FL
3	1		*BOOTLID KOMPRESSOR EMBLEM	Not Necessary	101.00 FL	*- FL
4	1		*BOOTLID C180 EMBLEM	Not Necessary	85.00 FL	*- FL
5	1		*BOOTLID C&C EMBLEM	Not Necessary	100.00 FL	*- FL
6	1		*BOOTLID CENTER CHROME	Not Necessary	436.00 FL	*- FL
7	2		*BOOTLID NO PLATE LAMP L+R	Not Necessary	196.00 FL	*- FL
8	1		*BOOTLID INNER TRIM	Not Necessary	563.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Not Necessary	399.00 FL	*- FL
10	2		*BOOTLID HINGE L+R	Not Necessary	348.00 FL	*- FL
11	2		*BOOTLID HINGE GARNISH L+R	Not Necessary	298.00 FL	*- FL
12	1		*BOOTLID LOCK	Not Necessary	349.00 FL	*- FL
13	1		*BOOTLID SWITCH	Not Necessary	298.00 FL	*- FL
14	1		*REAR WINDSCREEN MOULDING	Not Necessary	349.00 FL	*- FL
15	1		*REAR BUMPER	Repair	1,797.00 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	192.00 FL	*- FL
17	1		*REAR BUMPER CENTER CHROME	Serviceable	417.00 FL	*- FL
18	2		*REAR BUMPER SIDE CHROME L+R	Serviceable	508.00 FL	*- FL
19	1		*REAR BUMPER CENTER BRACKET	Not Necessary	330.00 FL	*- FL
20	2		*REAR BUMPER SIDE BRACKET L+R	Not Necessary	346.00 FL	*- FL
21	1		*REAR BUMPER UNDER COVER CENTER	Not Necessary	410.00 FL	*- FL
22	2		*REAR BUMPER UNDER COVER SIDE L+R	Not Necessary	478.00 FL	*- FL
23	1		*REAR REINFORCEMENT BAR	Not Necessary	1,506.00 FL	*- FL
24	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	79.00 FL	*- FL
25	2		*TAIL LAMP L+R	Not Necessary	1,762.00 FL	*- FL
26	2		*TAIL LAMP PANEL L+R	Not Necessary	958.00 FL	*- FL
27	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	368.00 FL	*- FL
28	2		*REAR FENDER L+R	Not Necessary	5,588.00 FL	*- FL
29	2		*REAR FENDER OUTER GARNISH L+R	Not Necessary	602.00 FL	*- FL
30	1		*REAR FENDER INNER PANEL LH	Not Necessary	1,789.00 FL	*- FL
31	2		*REAR FENDER INNER TRIM L+R	Not Necessary	1,892.00 FL	*- FL
32	2		*REAR FENDER INNER SHIELD L+R	Not Necessary	364.00 FL	*- FL
33	1		*REAR FENDER AIR DUCT LH	Not Necessary	101.00 FL	*- FL
34	1		*REAR WHEEL HOUSING LH	Not Necessary	1,829.00 FL	*- FL
35	1		*REAR END PANEL	Not Necessary	1,558.00 FL	*- FL
36	1		*REAR END PANEL TOP GARNISH	Not Necessary	463.00 FL	*- FL
37	1		*SPARE WHEEL PANEL	Not Necessary	2,421.00 FL	*- FL
38	2		*SPARE WHEEL QUARTER PANEL L+R	Not Necessary	1,552.00 FL	*- FL
39	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	569.00 FL	*- FL
40	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	492.00 FL	*- FL
41	1		*REAR EXHAUST PIPE	Not Necessary	2,227.00 FL	*- FL
42	1		*REAR EXHAUST MUFFLER	Not Necessary	980.00 FL	*- FL
43	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	226.00 FL	*- FL
44	1		*REAR EXHAUST MOUNTING	Not Necessary	101.00 FL	*- FL
45	1		*DRIVER SEAT BELT	Not Necessary	1,680.00 FL	*- FL
46	1		*FRONT PASSENGER SEAT BELT	Not Necessary	1,671.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*DRIVER SEAT BELT BUCKLE	Not Necessary	560.00 FL	*- FL
48	1		*FRONT PASSENGER SEAT BELT BUCKLE	Not Necessary	560.00 FL	*- FL
49	2		*REAR SEAT BELT LH/RH	Not Necessary	3,140.00 FL	*- FL
50	1		*DRIVER HEAD REST AIR BAG	Not Necessary	1,829.00 FL	*- FL
51	1		*FRONT PASSENGER HEAD REST AIR BAG	Not Necessary	1,789.00 FL	*- FL
52	1		*SRS CONTROL MODULE	Not Necessary	1,882.00 FL	*- FL
53	1		*REAR NUMBER PLATE & CASING	Not Necessary	100.00 FS	*- FS
54	1		*SET REAR REVERSE SENSOR	Serviceable	300.00 FS	*- FS
55	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
56	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
57	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
58	1		*BOOTLID CENTER CHROME CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*REAR BUMPER CHROME CLIPS	Not Necessary	50.00 FS	*- FS
61	1		*REAR BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
63	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
64	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
65	1		*REAR WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
66	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
68	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
69	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
70	1		*REAR FENDER OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
71	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
72	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	52,979.00	0.00
- List Item Discount on L Items 10.00/10.00% (\$)	5,073.90	0.00
Total Parts (\$)	47,905.10	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	0.00
6	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
7	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	120.00	0.00
8	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	0.00
9	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
10	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
11	TO RNR ALL AFFECTED SEAT BELTS TO FACILITATE REPAIRS	New	300.00	0.00
12	TO RNR DASHBOARD ASSY TO FACILITATE REPAIRS	New	600.00	0.00
13	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
14	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	1,000.00	0.00
Gross Labour Cost (S\$)			8,840.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >