

ASS. REC BY: T. J. M.


REF: CS/CTI 22012139/TWYS

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / VS / TP RES / OD RES / EVA / INV / MV  
To Inspect/Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 994K  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS WP  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMM 6134K Yr Regn: 2019 July  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Florida HRV C.C. 1496  
Colour: Silver A/C: Insured / Std / NI / NA  
Sp. Reading: — T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JHMK41820 JK 20863  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 215/60R16  
R: —  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Re Has  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 7/12/22  
Survey held at Ripost  
Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Battery weak</u>

Date/Time, File Pass to? ☐ : Preli. Report  
1) ☐ : Final Report  
Date/Time, File Return to?

2) \_\_\_\_\_  
Rep. Format : \_\_\_\_\_  
Lump Sum / L.B.H. (T) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
S + RS. \$	
Photos	
Others	
TOTAL	

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Repair Estimate**

Vehicle number: SMM6134K

Make &amp; Model: Honda HRV

Chassis number: JHMRU180JX201863

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ <i>bt</i> 910.50
2	Tailgate windscreen glass	1	\$ <i>bro</i> 739.80
3	Tailgate windscreen glass rubber moulding	1	\$ <i>nei</i> 78.60
4	Tailgate spoiler	1	\$ <i>R</i> 783.20
5	Tailgate outer garnish	1	\$ <i>cur</i> 189.90
6	Tailgate outer garnish emblem	1	\$ <i>nei</i> 18.50
7	Tailgate outer garnish emblem clips	2	\$ <i>nei</i> 12.00
8	Tailgate "HRV" emblem	1	\$ <i>nei</i> 23.00
9	Tailgate "IVTEC" emblem	1	\$ <i>nei</i> 16.60
10	Tailgate reverse camera	1	\$ <i>?</i> 718.20
11	Tailgate RH lamp assy	1	\$ <i>am</i> 287.50
12	Tailgate LH lamp assy	1	\$ <i>am</i> 287.50
13	Tailgate lock	1	\$ <i>?</i> 90.10
14	Tailgate lock catch	1	\$ <i>?</i> 21.30
15	Tailgate RH hinge	1	\$ <i>bt</i> 34.80
16	Tailgate LH hinge	1	\$ <i>bt</i> 34.80
17	Tailgate RH shock absorber	1	\$ <i>?</i> 199.00
18	Tailgate LH shock absorber	1	\$ <i>?</i> 199.00
19	Tailgate inner trim board	1	\$ <i>am</i> 112.00
20	Tailgate inner pull handle	1	\$ <i>?</i> 28.00
21	Tailgate weatherstrip	1	\$ <i>?</i> 105.20
22	Tailgate inner RH side garnish	1	\$ <i>?</i> 45.60
23	Tailgate inner LH side garnish	1	\$ <i>?</i> 45.60
24	Tailgate inner upper garnish	1	\$ <i>?</i> 781.00
25	Tailgate wiper motor	1	\$ <i>?</i> 452.10
26	Tailgate wiper arm cover	1	\$ <i>?</i> 8.40
27	Tailgate wiper arm	1	\$ <i>?</i> 43.70
28	Tailgate wiper blade	1	\$ <i>?</i> 42.20
29	Tailgate RH number plate lamp	1	\$ <i>?</i> 35.60
30	Tailgate LH number plate lamp	1	\$ <i>?</i> 35.60
31	Rear bumper	1	\$ <i>de</i> 598.70
32	Rear bumper RH reflector	1	\$ <i>?</i> 128.40
33	Rear bumper LH reflector	1	\$ <i>?</i> 128.40
34	Rear bumper RH side cover	1	\$ <i>de</i> 116.30
35	Rear bumper LH side cover	1	\$ <i>de</i> 116.30
36	Rear bumper RH side cover retainer	1	\$ <i>de</i> 22.00
37	Rear bumper RH side reverse sensor	1	\$ <i>dis</i> 114.20
38	Rear bumper RH centre reverse sensor	1	\$ <i>dis</i> 114.20
39	Rear bumper LH centre reverse sensor	1	\$ <i>dis</i> 114.20
40	Rear bumper LH side reverse sensor	1	\$ <i>dis</i> 114.20
41	Rear bumper reverse holders	4	\$ <i>nei</i> 141.10



42	Rear bumper lower cover	1	\$ ?	138.20
43	End panel	1	\$ ?	470.80
44	End panel inner garnish	1	\$ ?	66.50
45	End panel buzzer sensor	1	\$ ?	65.40
46	End panel antenna sensor	1	\$ ?	63.20
47	Rear spare tyre panel	1	\$ ?	701.20
48	Rear spare tyre panel insulator	1	\$ ?	128.20
49	Rear spare tyre panel top cover board	1	\$ ?	234.80
50	Rear spare tyre panel lower centre enforcement panel	1	\$ ?	118.20
51	Rear spare tyre panel jack up stiffener	1	\$ ?	78.20
52	Rear spare tyre panel tool sponge tray	1	\$ ?	192.20
53	Rear spare tyre panel RH extension panel	1	\$ ?	145.60
54	Rear spare tyre panel LH extension panel	1	\$ ?	145.60
55	Exhaust silencer	1	\$ ?	576.30
56	Exhaust silencer gasket	1	\$ ?	23.00
57	Exhaust silencer rubber mouldings	2	\$ ?	75.40
58	Exhaust silencer heat shield	1	\$ ?	47.80
59	Exhaust centre pipe	1	\$ ?	673.40
60	Exhaust centre pipe gasket	1	\$ ?	23.00
61	RH rear fender	1	\$ bu	549.70
62	RH rear fender quarter garnish	1	\$ de	45.20
63	RH rear fender arch moulding	1	\$ mi	172.20
64	RH rear fender inner trim board	1	\$ ?	172.20
65	RH rear fender splash shield	1	\$ de	67.90
66	LH rear fender	1	\$ bt	549.70
67	LH rear fender quarter garnish	1	\$ ?	45.20
68	LH rear fender arch moulding	1	\$ mi	172.20
69	LH rear fender inner trim board	1	\$ ?	172.20
70	LH rear fender splash shield	1	\$ ?	67.90
71	RH taillamp assy	1	\$ de	534.80
72	RH taillamp lock clips	1set	\$ x	23.00
73	RH taillamp sponge gasket	1	\$ x	24.00
74	RH taillamp panel	1	\$ bt	83.10
75	LH taillamp assy	1	\$ de	534.80
76	LH taillamp lock clips	1set	\$ x	23.00
77	LH taillamp sponge gasket	1	\$ x	24.00
78	LH taillamp panel	1	\$ bu	83.10
79	Rear RH door	1	\$ ?	930.60
80	Rear RH door frame black sticker	1	\$ ?	35.00
81	Rear RH door lock	1	\$ ?	193.40
82	Rear RH door lock catch	1	\$ ?	32.00
83	Rear RH door inner trim board	1	\$ ?	450.30
84	Rear RH door inner weatherstrip	1	\$ ?	93.40
85	Rear LH door	1	\$ ?	930.60
86	Rear LH door frame black sticker	1	\$ ?	35.00
87	Rear LH door lock	1	\$ ?	193.40
88	Rear LH door lock catch	1	\$ ?	32.00
89	Rear LH door inner trim board	1	\$ ?	450.30
90	Rear LH door inner weatherstrip	1	\$ ?	93.40
91	Bonnet	1	\$ bt	845.10
92	Bonnet RH hinge	1	\$ bt	42.60
93	Bonnet LH hinge	1	\$ bt	42.60
94	Bonnet lock	1	\$ bt	60.80
95	Bonnet inner heat insulator	1	\$ de	118.00
96	Bonnet RH rubber seal	1	\$ ?	21.00
97	Bonnet LH rubber seal	1	\$ ?	21.00
98	Bonnet inner RH centre rubber moulding	1	\$ ?	22.00

99	Bonnet inner LH centre rubber moulding		1	\$ ?	22.00
100	Front bumper		1	\$ de	507.10
101	Front bumper RH fog lamp		1	\$ de	237.40
102	Front bumper RH fog lamp cover		1	\$ de	22.90
103	Front bumper RH fog lamp bracket		1	\$ de	53.30
104	Front bumper LH fog lamp		1	\$ de	237.40
105	Front bumper LH fog lamp cover		1	\$ de	22.90
106	Front bumper LH fog lamp bracket		1	\$ de	53.30
107	Front bumper lower cover		1	\$ de	247.00
108	Front bumper lower grille		1	\$ de	84.30
109	Front bumper tow cover		1	\$ de	15.40
110	Front bumper air guide		1	\$ ?	30.40
111	Front bumper reinforcement		1	\$ de	237.80
112	Front bumper reinforcement garnish		1	\$ de	28.10
113	Front bumper reinforcement RH garnish		1	\$ ?	8.20
114	Front bumper reinforcement LH garnish		1	\$ ?	8.20
115	Front bumper RH side retainer		1	\$ de	11.70
116	Front bumper LH side retainer		1	\$ de	11.70
117	Front grille		1	\$ cur	288.90
118	Front grille upper moulding		1	\$ cur	202.40
119	Front grille moulding		1	\$ cur	46.50
120	Front grille bracket		1	\$ cur	42.10
121	Front grille emblem		1	\$ cur	30.50
122	Front grille emblem clips		2	\$ cur	8.00
123	Support panel		1	\$ bt	463.50
124	Support panel top cover		1	\$ de	145.00
125	Front RH fender		1	\$ bt	589.00
126	Front RH fender splash shield		1	\$ x	114.00
127	Front RH fender arch moulding		1	\$ ?	186.00
128	Front RH fender inner extension panel		1	\$ RP	153.20
129	Front RH fender inner extension lower panel		1	\$ RP	89.00
130	Front RH fender inner extension lower side panel		1	\$ RP	176.30
131	Front RH fender inner wheel housing panel		1	\$ RP	433.20
132	Front LH fender		1	\$ RP	589.00
133	Front LH fender splash shield		1	\$ x	114.00
134	Front LH fender arch moulding		1	\$ x	186.00
135	RH headlamp		1	\$ cur	1,952.70
136	RH headlamp side bracket		1	\$ de	18.70
137	RH headlamp lower bracket		1	\$ de	43.00
138	LH headlamp		1	\$ cur	1,952.70
139	LH headlamp side bracket		1	\$ de	18.70
140	LH headlamp lower bracket		1	\$ de	43.00
141	Aircon condenser		1	\$ bt	568.10
142	Aircon suction pipe		1	\$ ?	132.20
143	Aircon discharge pipe		1	\$ ?	119.30
144	Aircon receiver		1	\$ ?	119.30
145	Aircon fan cowling		1	\$ ?	90.90
146	Aircon fan blade		1	\$ ?	61.60
147	Aircon fan motor		1	\$ ?	322.60
148	Radiator assy		1	\$ bt	1,291.70
149	Radiator fan cowling		1	\$ ?	115.80
150	Radiator fan blade		1	\$ ?	61.60
151	Radiator fan motor		1	\$ ?	322.60
152	Radiator LH side garnish		1	\$ ?	43.20
153	Radiator RH side garnish		1	\$ ?	43.20
154	Radiator spare tank		1	\$ ?	92.10
155	Radiator upper filler hose		1	\$ ?	35.00



156	Radiator lower hose		1	\$ ?	45.30
157	Radiator upper hose		1	\$ ?	38.70
158	Ambient sensor clips		1	\$ ?	4.60
159	Air intake duct		1	\$ ?	46.80
160	Horn (high tone)		1	\$ ?	34.70
161	Horn (low tone)		1	\$ ?	34.70
162	Washer tank		1	\$ <del>dep</del>	61.10
163	Washer tank motor		1	\$ X	65.90
164	Front audible speaker		1	\$ X	92.00
165	Air cleaner box lower cover		1	\$ ?	189.00
166	Air cleaner box upper cover		1	\$ ?	73.40
167	Engine under cover		1	\$ ?	98.30
168	Engine intake manifold		1	\$ ?	564.10
169	Engine intake manifold hose		1	\$ ?	28.70
170	Engine oil dip stick		1	\$ ?	22.70
171	Engine thermostat cover		1	\$ ?	88.10
172	Front wire harness		1	\$ ?	1,683.20
173	Front windscreen glass		1	\$ <del>cur</del>	983.60
174	Front windscreen glass rubber moulding		1	\$ <del>cur</del>	93.20
175	Front wiper garnish		1	\$ ?	193.00
176	Front RH wiper garnish side cover		1	\$ ?	21.00
177	Front LH wiper garnish side cover		1	\$ ?	21.00
178	Front RH airbag sensor		1	\$ <del>aut</del>	187.30
179	Front LH airbag sensor		1	\$ <del>aut</del>	187.30
180	Airbag control unit		1	\$ <del>aut</del>	1,894.30
181	Steering airbag		1	\$ <del>aut</del>	1,605.40
182	Steering airbag spiral sensor		1	\$ <del>aut</del>	298.00
183	Dashboard LH airbag		1	\$ <del>aut</del>	2,246.80
184	Dashboard		1	\$ <del>de</del>	873.20
185	Driver seat belt		1	\$ <del>aut</del>	687.90
186	Driver seat belt buckle		1	\$ ?	184.00
187	Front LH passenger seat belt		1	\$ ?	687.90
188	Front LH passenger seat belt buckle		1	\$ ?	184.00
189	Rear LH passenger seat belt		1	\$ ?	633.50
190	Rear LH passenger seat belt buckle		1	\$ ?	184.00
191	Rear RH passenger seat belt		1	\$ ?	633.50
192	Rear RH passenger seat belt buckle		1	\$ ?	184.00

	\$	48,338.90
Parts less 20%	\$	9,667.78
Total	\$	38,671.12

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate inner trim board clips	1set	\$ <del>30</del> 80.00
2	Tailgate windscreen glass sealant	1	\$ <del>40</del> 80.00
3	Tailgate windscreen glass inner seal	1	\$ <del>30</del> 60.00
4	Tailgate windscreen glass solar flim	1	\$ X 650.00
5	Rear bumper clips	1set	\$ <del>30</del> 80.00
6	Rear bumper lower cover clips	1set	\$ <del>20</del> 50.00
7	RH rear fender quarter garnish clips	1set	\$ X 35.00
8	RH rear fender arch moulding clips	1set	\$ X 50.00
9	RH rear fender inner trim board clips	1set	\$ X 60.00
10	RH rear fender splash shield clips	1set	\$ X 50.00
11	LH rear fender quarter garnish clips	1set	\$ X 35.00

12	LH rear fender arch moulding clips	1set	\$ 2000	50.00
13	LH rear fender inner trim board clips	1set	\$ ?	60.00
14	LH rear fender splash shield clips	1set	\$ ?	50.00
15	Spare tyre panel joint sealant	1	\$ x	80.00
16	Rear spare tyre panel RH extension panel joint sealant	1	\$ x	60.00
17	Rear spare tyre panel LH extension panel joint sealant	1	\$ x	60.00
18	End panel joint sealant	1	\$ 4000	60.00
19	End panel inner garnish clips	1set	\$ 2000	50.00
20	LH taillamp panel joint sealant	1	\$ 720	50.00
21	RH taillamp panel joint sealant	1	\$ 3000	50.00
22	Rear in car recorder	1	\$ ?	750.00
23	Rear number plate	1	\$ 61-45	70.00
24	Rear RH door inner trim board clips	1set	\$ x	50.00
25	Rear LH door inner trim board clips	1set	\$ x	50.00
26	Front windscreen glass sealant	1	\$ 4000	80.00
27	Front windscreen glass inner seal	1	\$ 3000	60.00
28	Front windscreen glass ERP bracket	1	\$ net	26.00
29	Front windscreen glass solar flim	1	\$ x	650.00
30	Front RH fender inner extension panel joint seal	1	\$ x	60.00
31	Front RH fender inner extension lower panel joint seal	1	\$ x	60.00
32	Front RH fender inner extension lower side panel joint seal	1	\$ x	60.00
33	Front RH fender inner wheel housing panel joint seal	1	\$ x	80.00
34	Radiator coolant	1	\$ 44-40	80.00
35	Front number plate	1	\$ 61-45	70.00
36	Engine under cover clips	1set	\$ x	70.00
37	Bonnet inner heat insulator clips	1set	\$ 2000	80.00
38	Front bumper clips	1set	\$ 3000	80.00
39	Front bumper lower cover clips	1set	\$ x	80.00
40	Front grille clips	1set	\$ 2000	60.00
41	Support panel top cover clips	1set	\$ x	50.00
42	Front RH fender splash shield clips	1set	\$ x	50.00
43	Front RH fender arch moulding clips	1set	\$ x	60.00
44	Front LH fender splash shield clips	1set	\$ x	50.00
45	Front LH fender arch moulding clips	1set	\$ x	60.00
Total:				\$ 4,586.00

No.	Labour and painting		Amount S\$
<b>(Rear portion)</b>			
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	1400	\$ 2,500.00
2	Spray painting on affected areas and panels	1400	\$ 2,000.00
3	Check wiring and lighting system on affected areas	40	\$ 180.00
4	Apply rust coating chemical on affected areas and panels	50	\$ 200.00
5	To remove and reinstall tailgate windscreen glass to assist repair	120	\$ 250.00
6	To remove and replace reverse camera to assist repair	30	\$ 180.00
7	To remove and replace tailgate inner mechansim to new tailgate	62	\$ 180.00



8	Remove and replace rear bumper reverse sensor to assist repair		\$ 30	10.00
9	Remove and replace rear inner trim, garnish and boards to assist repair		\$ 60	450.00
10	Remove and replace exhaust silencer, centre pipe and gaskets to assist repair		\$ 80? photo	320.00
11	Remove and replace rear bumper reverse sensors to assist repair		\$ X	100.00
12	Remove and reinstall fuel tank pipes, hoses and sensors to assist repair		\$ 780	200.00
13	Remove and reinstall seats, roof lining and carpets to assist repair		\$ 80	450.00
14	Mount vehicle on chassis alignment bench to repair chassis frames	photo	\$ 7250	500.00
15	Remove and replace rear RH door inner mechanism to new door		\$ 60?	200.00
16	Remove and replace rear LH door inner mechanism to new door		\$ 60?	200.00
<b>(Front portion)</b>				
17	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	800	\$	1,800.00
18	Spray painting on affected areas and panels	1000	\$	1,600.00
19	Check wiring and lighting system on affected areas		\$ 30	100.00
20	Apply rust coating chemical on affected areas and panels		\$ 40	180.00
21	Remove and replace aircon condenser, pipes and fan assy to assist repair		\$ 100	280.00
22	Remove and replace radiator assy, pipes, hoses and fan assy to assist repair		\$ 100	280.00
23	Refocus and adjust headlamps assy		\$ 30	100.00
24	Remove and replace front windscreen glass to assist repair		\$ 120	280.00
25	Remove and replace airbag system and seat belts to assist repair		\$ 200	500.00
26	Reset and diagnose control unit and fault codes		\$ 200?	450.00
			Total:	\$ 13,490.00

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Spare Parts: \$ 38,671.12  
Special Nett: \$ 4,586.00  
Labour: \$ 13,490.00

**Total Amount: \$ 56,747.12**

Auto Consultants hence notify  
Repairer of the following:  
Resurvey before/after spray painting  
display damaged part(s) during resurvey  
parts prices are subject to confirmation  
third party survey is on a "Without Prejudice" basis  
no illegal modification(s) is allowed  
supplementary item(s) must be resurveyed and  
subject to final approval from Insurance Company

knownedged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Tanfimi 97495749  
WP 7/12/22 E1115  
4/5 Resurvey after repair  
- To check repair limit  
- To check consistency of accident  
- To check part prices  
18 days  
Tanfimi @ khantow.com

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 864F

### Vehicle Details

Vehicle No.: SMM6134K  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 04 Dec 2022  
Vehicle Make: HONDA  
Vehicle Model: HRV 1.5 DX CVT  
Primary Colour: Silver  
Manufacturing Year: 2019  
Engine No.: L15B5671865  
Chassis No.: JHMRU1810JX201863  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$20,361.00  
Original Registration Date: 05 Jul 2019  
First Registration Date: 05 Jul 2019  
Transfer Count: 0  
Actual ARF Paid: \$20,506.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 04 Jul 2029  
PARF Rebate Amount: \$15,379.00

### Intended COE Rebate Details

COE Expiry Date: 04 Jul 2029  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$30,009.00  
COE Rebate Amount: \$19,755.00  
**Total Rebate Amount: \$35,134.00**

The information contained herein is correct as at 03 Dec 2022

OK



Date of Accident : 2/Dec/2022 Accident Time: 2050 HRS (24-HR-FORMAT)  
Accident Place : CTE (SLE) before Jalan Bahagia  
Vehicle Reg. No (Car plate No.) : SMM 6134E CC : Vehicle Make/Model: Honda Vezel  
Insurance Company : India International Policy No. : \_\_\_\_\_  
Name of Registered Owner : Company / Individual Tan Siok Lee  
ID of Registered Owner : Co Reg No: -1- Owner's NRIC No: S7322864F  
OWNER EMAIL ADDRESS: -1- : Co Contact No: -1- Owner's Contact No: 97387375

**DRIVER'S Name** : Ang Pang Ngin **DRIVER'S NRIC No:** S7237436C

**DRIVER'S Date of Birth** : 11/10/1972 **DRIVER'S License Pass Date** 20/04/1998

**Relationship bet. Owner & Driver** : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: -1-

**DRIVER'S Address** : 20 Jalan Setia, S (368438)

**DRIVER'S Contact No./ Alt No.** : 1) 9437 2314 2) \_\_\_\_\_

**DRIVER'S Occupation** : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)

**Email Address** : PANG NGIN@GMAIL.COM

**Weather & Road Surface** : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

**Reporting Type** : Reporting Only \ Claim Other Party \ Claim Own Insurance

**Number of Passengers (including Driver):** 1 **Name & Gender:** -1-

**Was the accident reported to the police?** YES \ NO

**Was there any video Captured by car camera:** YES \ NO

**Exact purpose for which vehicle was being used at the time of accident:** Private use \ Work purpose

**Any injuries, if yes (name of the injured person)** \_\_\_\_\_

**Other Party Driver's Particulars (if any)**

**Vehicle Reg No:** GBE 725S (4th vehicle) **Vehicle Reg No:** SNA2424B (2nd vehicle)

**Vehicle Make/Model:** Nissan Cabstar **Vehicle Make/Model:** Hyundai i30

**Name DRIVER:** \_\_\_\_\_ **Name DRIVER:** \_\_\_\_\_

**IC No. DRIVER:** \_\_\_\_\_ **IC No. DRIVER:** \_\_\_\_\_

**DRIVER'S Contact & add:** \_\_\_\_\_ **DRIVER'S Contact & add:** \_\_\_\_\_

**REPORT FORM EXPLAINED IN :** ENGLISH / CHINESE / MALAY / TAMIL OTHERS: \_\_\_\_\_

**WHO REPORTED THE ACCIDENT :** OWNER / DRIVER / BOTH

S4H194P Honda Shuttle (1st vehicle)



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

### Sketch Plan




Describe Circumstance of the Accident


Refer to attached police report.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel





# SINGAPORE POLICE FORCE

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20221203/7002

1 of 3

Report No. T/20221203/7002

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/12/2022 00:25	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: ONG PANG NGIN		Address: 20 JALAN SETIA SINGAPORE 368438	
ID Type / ID No.: NRIC NO / S7237436C		Contact No.: Home/Office:	Mobile: 94372314
Nationality: SINGAPORE CITIZEN		Email: PANGNGIN@GMAIL.COM	
Sex: Male	Age: 50	Date of Birth: 11/10/1972	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Manufacturing Manager		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident			
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/12/2022 20:50
Location:  WHAMPOA DRIVE		Type of Location: Straight Road	
Weather: Clear		Road Surface: Dry	Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate
Type of Collision: Chain		Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
GBE725S	Lorry	NISSAN	Cabstar	Silver	Seriously Damaged	0
SLH194P	Car	HONDA	Shuttle	Silver	Seriously Damaged	0
SMM6134K	Car	HONDA	HRV	Silver	Seriously Damaged	0



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20221203/7002

2 of 3

Report No. T/20221203/7002

**CONTINUATION OF REPORT**

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
SNA2424B	Car	HYUNDAI	i30	Black	Seriously Damaged	0

Details of Person Involved					
Any Pedestrian Involved: No					
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA		
Driver					
Name	ONG PANG NGIN			ID No.	S7237436C
Related Vehicle	SMM6134K (Car)			Contact No.	94372314
Hospital/Clinic	24 HOUR WALK-IN CLINIC			Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	03/12/2022		Date	03/12/2022	
No. of Days granted Medical Leave		03	Degree of	Slight	

**Brief Details.**

I was travelling on the 4th lane of the 5 lane road when a lorry collided into the rear of my vehicle, which caused it to surge forward and hit another two vehicles in front. I have retrieved my in-car footage for insurance claims purposes and I have also sought medical attention thereafter at 12.20am 3rd of Dec as I'm feeling strains over my neck and back area, and have suffered several contusions over my right elbow and left knee.

The order of the vehicles are as such

1st vehicle : SLP194P

2nd vehicle : SNA2424B

3rd vehicle : SMM6134K

4th vehicle : GBE725S



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20221203/7002

3 of 3

Report No. T/20221203/7002

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
MUHAMMAD AFIQ BIN RAHMAT  
Contact No.: 65476171

NP168

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:  
03/12/2022 00:25

Classification Of Case: