

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	01/12/2022
Vehicle Reg. No.:	SMG9917E	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A)	Vehicle Reg. Date:	08/01/2019
Vehicle Colour:	Black		
Engine No:	A2172908GKCX0153	Chassis No:	W0VZM6EF6J1068736
Odometer:	270401 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	9,386.30
Miscellaneous Items	119.00
Labour	2,120.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	11,625.30
- Excess (S\$)	2,000.00
(S\$)	9,625.30
+ GST 7.00% (S\$)	673.77
Nett Amount (S\$)	10,299.07

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Dec 2022)

Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SMG9917E/02/12/2022 14:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39214206	*FRONT BONNET	0.00	0.00	*1,705.00 F
2	1	39107929	*FRONT RADIATOR GRILLE	0.00	0.00	*299.00 F
3	1	13491196	*FRONT RADIATOR GRILLE MOULDING (CHROME)	0.00	0.00	*274.00 F
4	1	13491204	*FRONT LOGO EMBLEM	0.00	0.00	*75.00 F
5	1	39159651	*FRONT BUMPER	0.00	0.00	*1,158.00 F
6	1	39098178	*FRONT BUMPER SPONGE	0.00	0.00	*107.00 F
7	1	13460223	*FRONT FOGLAMP LH	0.00	0.00	*253.00 F
8	1	39138751	*FRONT FOGLAMP COVER LH	0.00	0.00	*145.00 F
9	1	13491269	*INSERT, CHROME, FRONT FOGLAMP LH	0.00	0.00	*537.00 F
10	1	39210099	*FRONT HEADLAMP LH	0.00	0.00	*1,161.00 F
11	1	13491381	*HEADLAMP BRACKET LH	0.00	0.00	*47.00 F
12	2	95515167	*FRONT PARKING SENSOR	0.00	0.00	*410.00 F
13	1		*FRONT BUMPER WIRING HARDNESS	0.00	0.00	*323.00 F
14	1	39108782	*FRONT PEDESTRIAN CRASH SENSOR	0.00	0.00	*342.00 F
15	1	39125439	*FRONT FENDER LH	0.00	0.00	*597.00 F
16	1		*FRONT FENDER INNER SHIELD OUTER	0.00	0.00	*220.00 F
17	1	13312747	*Tyre rim - Alloy Rim	0.00	0.00	*458.00 F
18	1	39209192	*Headlamp Control Module LH	0.00	0.00	*422.00 F

F=Franchise part.

Sub Total (S\$)	8,533.00
+ Margin on L,N Items 10.00% (S\$)	853.30
Total Parts (S\$)	9,386.30

Munich Autocare Pte Ltd/SMG9917E/02/12/2022 14:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	7	BUMPER CLIP	49.00
2	10	FENDER INNERSHIELD CLIP SET	70.00
Sub Total (S\$)			119.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISMANTLE FRONT ACCIDENT POTION, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, AND ALL THE EFFECRED AREA.	New	1,000.00
2	TO DISMANTLE & RENEW FRONT PARKING SENSOR	New	120.00
3	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION INCLUDING ADJUST OF HEADLAMP	New	120.00
4	TO CONDUCT 4 WHEEL ALIGNMENT	New	80.00
5	TO RESPRAY FRONT ACCIDENT POTION, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH ,AND ALL THE EFFECTED AREA	New	800.00
Gross Labour Cost (S\$)			2,120.00

Munich Autocare Pte Ltd/SMG9917E/02/12/2022 14:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >