Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Alfred Toh Date: 07 Dec 2022

Preliminary Advice

Vehicle No : SMZ7077S Accident Date : 24/11/2022

Make : JAGUAR XE 2.0 I4D TSS Policy No.

DMPCSNW00053962200

Assignment Date : 05/12/2022 Excess : \$\$0.00 Date of Inspection : 06/12/2022 Est. Duration of Repair : 0

Inspection At : AUTO INSURE PTE LTD (HQ) (WOODLANDS)

6 MARSILING LANE SINGAPORE 739145

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 79,000.00

 COE / PARF Rebate
 :S\$ 51,668.00

Salvage Value :S\$

Margin for Repair :S\$ 27,332.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :