



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2300085

INV Date 06/01/2023

Reference CS/EQI22012153/Rvy3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SBS 3448Z

Insured Veh. SKJ 9928G

Claim No. DM22HO02028

Policy No.

Accident Date 20/11/2022

Inspection Date 06/12/2022

Description	Total
Survey Inspection	160.00
Digital Photographs	
Transportation	
Subtotal	160.00
GST (8%)	12.80
Grand Total	172.80

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS/EQI22012153/Rvy3e2 Date: 06/01/2023 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKJ 9928G	Veh. Inspected	SBS 3448Z
Policy No.		Coverage (\$)	0.00
Claim No.	DM22HO02028	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	05/12/2022
2. Vehicle Particulars & Condition			
Make & Model	VOLVO B9TL 9.4L AUTO	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	YV3S4P920FA169353	Colour	GREEN
Odometer	494777 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/11/2022	Inspection Date	06/12/2022
Survey held at	154 GUL CIRCLE, 629611 Tuas		
Repairer	BOXFRESH PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 3448Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	O/S REAR SIGNAL LIGHT P/N: ELU-00300	SCRATCHED	259.40	259.40
1	RED REFLECTOR LAMP P/N: ELU 0430	CRACKED	10.00	10.00
			269.40	269.40
	<u>LABOUR</u>			
	REMOVAL OF OS REAR PANEL STICKERS. }		600.00	500.00
	REPAIR O/S REAR PANEL. }		-	-
	PANEL BEATING OF REAR BUMPER. }		-	-
	SAND, PUTTY AND MAKE GOOD SURFACE OF AFFECTED PARTS. }		-	-
	PAINTING OF AFFECTED PARTS. }		-	-
			600.00	500.00
	GRAND TOTAL		869.40	769.40
	RECOMMENDED COST OF REPAIRS			769.40

Report Ref No. CS/EQI22012153/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/11/2022 14:24 (SGT)
Reported by Both
Date of Accident 20/11/2022 20:48 (SGT)
Exact Location of Accident Upper E Coast Rd & Bedok South Ave 1, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBS3448Z

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Go Ahead Singapore Pte Ltd
Company Reg No 2XXXXX900C
Email Address claimsmatter@go-aheadsingapore.com
Mobile Phone No (Phone) +65-63847169
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Volvo
Model B9tl
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Bus
Transmission Auto
CC 9400

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Policy Number / Cover Note Number D-19094111MFB

DRIVER

Name of Driver Hassan Bin Ali
NRIC No SXXXX299F
Date Of Birth 24/10/1969
Occupation Outdoor

Date Of Driving Pass	22/03/2019
Driving experience	3 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88451864
Alt. Phone Number	-
Email Address	claimsmatter@go-aheadsingapore.com
Address	535 Hougang Street 52
Address complement	#02-10
Postcode	530535
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

BC Hassan was driving service 43 [SBS3448Z] on the above-mentioned date & time. While stationary at the above-mentioned location, the front left corner bumper & h/lamp of a dark blue BMW X4 [SKJ9928G] rear-ended SBS3448Z's rear right corner panel & reverse light

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	DIFFERENT FORMAT

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ9928G
Vehicle Manufacturer	BMW
Vehicle Model	X4
Vehicle Variant	-
Vehicle Colour	Blue

Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBS 3448Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

