



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP) ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675			Ref: CS/SPF22012158/y3 Date: 05/12/2022 Code: SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 1890M	Veh. Inspected	SLS 352J	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/105	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	05/12/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2022	Inspection Date		
Survey held at	KAN FOOK SING MOTOR WORKSHOP BLK.8 JTC DEFU INDUSTRIAL CITY #04-29 DEFU SOUTH STREET 1 SINGAPORE 533758			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				