

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22012160/Tqy3e2
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	15/02/2023
				Code:	SMR
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 181E	Veh. Inspected	t	SCQ 8776S
	Policy No.		Coverage (\$)		0.00
	Claim No.	TAX/12/22/2006	Excess (\$)		0.00
	Assign From	HUA YEN	Assign Date		05/12/2022
2.	Vehicle Particulars & Condition				
	Make & Model	B.M.W. X5	c.c		2979
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	WBAKR020400C46769	Colour		BLACK
	Odometer	54705 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	315/35 R19	PIRELLI		6 mm
	L/H Front Tyre	315/35 R19	PIRELLI		6 mm
	R/H Rear Tyre	315/35 R19	PIRELLI		6 mm
	L/H Rear Tyre	315/35 R19	PIRELLI		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	. General Information				
	Accident Date	01/12/2022	Inspect Date /	Time	06/12/2022 (09:52 AM)
	Survey held at	LUCK7WIN PTE LTD	•		
	51 UBI AVENUE 1 #01-11 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		7 Worki	ing Days

Report Ref No. CS3/SMR22012160/Tqy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

M.MATAI, AMSAE-A

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.