

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En	Automo	CO3/31	MR22006800
	STRIDES AUTOM		Ref:	CS2/SMP22/	006800/y3	
	60 WOODLANDS E4SINGAPORE 75		Date:	18/07/2022	05/12/2022	
			1	Code:	SMR	
١.		Policy Particulars	:- (THIRD PARTY	CLAIN	<b>1</b> )	
	Insured Veh.	SHB 1330K	Veh. Inspected		SLV 8444S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/07/22/2040	Excess (\$)		0.00	
	Assign From	HUA YEN- ANA MAGNAYE	Assign Date		10/07/2022	05/12/2022
2.		Vehicle Parti	culars & Condition	on		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
		Condit	ions of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
•		Descripti	on of Damages			
) <b>.</b>	1		I Information			
	Accident Date	15/07/2022	Inspection Date	•		
	Survey held at					
	160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722					
ōa.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					