



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22006592/Dqy3e2-1	
			Date: 06/01/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1137C	Veh. Inspected	FBQ 7711Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/22/2063	Excess (\$)	0.00
	Assign From	ANA MAGNAYE	Assign Date	05/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FS150F	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	PMKKC27A0KB212603	Colour	ORANGE
	Odometer	67048 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/80-19	DUNLOP	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90-19	DUNLOP	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/06/2022	Inspection Date	12/07/2022
	Survey held at	RIGHT CLICK AUTOWORKS PTE LTD 7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	