

Mon 20/02 @ 10AM

S&R ✓

SJP2598B

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

05 DEC 2022

Estimate No. : b1 64258
Date Estimated : 05/12/2022
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Fullmer Michael Keith
53 Pipit Road
#06-96

Singapore 370053

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP2598B	WBA5A52010D823541	13/05/2015	528iA	39982

DESCRIPTION

To replace rear bumper, left rear fender, left trunk floor panel including to pull & straighten rear left fender before cutting and to knock out dented area

5100 5,950.00

To respray rear bumper, left rear fender, left roof frame, tail panel and boot compartment

3463 3,645.00

To carry out body cavity preservation.
(For cut panel).

504 531.00

To remove and install boot compartment carpet and garnish to facilitate repair.

257 271.00

To remove and install rear windscreen glass to facilitate repair.

✓ 574.00

To supply and install rear windscreen solar film.

? 531.00

To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.

504 531.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

Sundries.

✓ 150.00

Total Labour 1: 12,360.00

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT FOR COARSE THREADED PIN	10	0.85	8.50
# EXTENSION FOR REAR LH WHEEL	1	1,099.10	1,099.10
# RR LH FENDER	1	2,232.65	2,232.65
REINFORCEMENT PLATE C PILLAR LH	1	54.80	54.80
REINFORCEMENT PLATE ROCKEL PANEL LH	1	54.80	54.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 64258
Date Estimated : 05/12/2022
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP2598B	WBA5A52010D823541	13/05/2015	5281A	39982

DESCRIPTION	QTY	PRIC	VALUE
T WELD BOLT L=5.4MM	10	0.90	9.00
# RR LH MOUNT	1	199.70	199.70
# RR RH MOUNT	1	199.70	199.70
# REAR BUMPER PRIMED (PDC)	1	1,616.00	1,616.00
# RR WINDOW GREEN	1	882.65	882.65
# RR LH LIGHT IN THE SIDE PANE	1	638.00	638.00
BLIND RIVET AVIBVLB	15	0.55	8.25
SCREW (SF PLUS M5X15)	5	0.60	3.00
PUNCH RIVET N5	20	0.55	11.00
(DG) BODYWORK ADHESIVE K5A (50ML)	1	121.90	121.90
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
PUNCH RIVET N4	2	0.55	1.10
(DG/SL) BODY ADHESIVE K5 (195 ML)	1	353.50	353.50
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	1	27.85	27.85
(SL/DG) SEALANT D2 290ML	3	32.10	96.30

Total Parts : 7,907.05

Tanpin 97495249
WP 2/2/25 C 1115
Repair after repair
Tanpin elkhambou.
9-10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	12,360.00
Parts	:	7,907.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,418.89
Grand Total	:	21,685.74

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **