



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300781

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/02/2023
Reference CC6/CTI22012171/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKS 7971X
Insured Veh. SNB 7320D
Claim No. SNM22D208688/C02
Policy No. DMPCSNW00211112201
Accident Date 02/12/2022
Inspection Date 06/12/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22012171/Upa3q2 Date: 10/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNB 7320D	Veh. Inspected	SKS 7971X
	Policy No.	DMPCSNW00211112201	Coverage (\$)	0.00
	Claim No.	SNM22D208688/C02	Excess (\$)	0.00
	Assign From		Assign Date	06/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ACCORD (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MRHCM46407P020089	Colour	SILVER
	Odometer	254919 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	7 mm
	L/H Front Tyre	215/60 R16	MICHELIN	7 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	7 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/12/2022	Inspection Date	06/12/2022
	Survey held at	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 7971X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	DENTED / BUCKLED	1,387.10	875.20
1	REAR BOOT LOCK	BENT	302.20	199.80
1	REAR BOOT LOCK CATCH	NOT NECESSARY	65.20	-
1	REAR BOOT EMBLEM (ACCORD)	NECESSARY	47.00	47.00
1	REAR BOOT CENTRE EMBLEM	NECESSARY	45.20	38.00
1	REAR BOOT EMBLEM (2.0 I.VTEC)	NECESSARY	58.00	35.00
1	REAR BOOT THIRD BRAKE LAMP	NOT NECESSARY	636.00	-
2	REAR BOOT REVERSE LAMP @\$486.00	N/S CRACKED	972.00	241.20
1	REAR BOOT RUBBER	TWISTED	248.50	188.50
2	REAR BOOT HINGES @\$113.50	TO REPAIR SEE LABOUR	227.00	-
1	REAR BOOT INNER COVER	NOT NECESSARY	325.00	-
1	REAR NUMBER PLATE LAMP GARNISH	CRACKED	134.50	134.50
2	REAR NUMBER PLATE LAMP @\$37.00	NOT NECESSARY	74.00	-
2	REAR TAIL LAMP @\$682.10	CRACKED	1,364.20	850.00
2	REAR TAIL LAMP LOWER BRACKET @\$36.50	NOT NECESSARY	73.00	-
2	REAR TAIL LAMP PANEL @\$176.40	N/S BENT	352.80	176.40
1	REAR END PANEL	BADLY DENTED	895.20	366.20
1	REAR END PANEL TOP GARNISH	TWISTED	213.20	162.50
1	REAR BUMPER	DISTORTED	1,621.30	845.20
1	REAR BUMPER REINFORCEMENT	NOT FITTED	485.60	-
2	REAR BUMPER SIDE RETAINER @\$25.90	N/S BENT	51.80	25.90
2	REAR BUMPER CHROME GARNISH @\$117.00	N/S CRACKED	234.00	86.50
4	REAR BUMPER REVERSE SENSOR @\$245.00	SHORTED (2PCS ONLY)	980.00	320.00
1	REAR BUMPER EXHAUST COVER	NOT NECESSARY	103.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,352.20	-
1	REAR SPARE TYRE TOP COVER BOARD	TORN	391.50	391.50
1	REAR FLOOR PANEL TOOLS SPONGE	TORN	365.30	288.50
1	REAR SPARE TYRE LOCK SCREW	NOT NECESSARY	76.20	-

Report Ref No. CC6/CTI22012171/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,175.70	-
2	REAR EXHAUST RUBBER @\$25.80	NOT NECESSARY	51.60	-
1	REAR EXHAUST CHROME PIPE	NOT NECESSARY	123.20	-
2	REAR FENDER @\$1482.00	TO REPAIR SEE LABOUR	2,460.40	-
2	REAR FENDER INNER GARNISH @\$381.20	N/S TORN	762.40	304.20
2	REAR FENDER AIR DUCT @\$69.20	NOT NECESSARY	1,384.40	-
	LESS 20% DISCOUNT		-3,807.74	-1,115.22
			15,230.96	4,460.88
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	40.00	-
10	REAR BOOT INNER COVER CLIPS @\$5.00 (SN)	NOT NECESSARY	50.00	-
3	REAR END PANEL TOP GARNISH CLIPS @\$5.00 (SN)	NOT NECESSARY	15.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR SPARE TYRE PANEL TOP INSULATOR (SN)	NOT NECESSARY	250.00	-
12	REAR FENDER INNER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
			595.00	50.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		200.00	20.00
	TUFF KOTE.		250.00	60.00
	TO REMOVE AND REFIX UPHOLSTERY CUSHION SEAT.		250.00	80.00
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	160.00	-
	TO REMOVE AND REPLACE EXHAUST PIPE.	NOT NECESSARY	160.00	-
	TO REMOVE AND REPLACE REVERSE SENSOR.		250.00	50.00
	TO REMOVE AND REFIX REAR BOOT GARNISH ITEM.		200.00	60.00
	TO REMOVE AND REPLACE SPARE PARTS AND PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BOOT HINGES, REAR SPARE TYRE PANEL AND REAR FENDER.		2,000.00	800.00
	TO SPRAY PAINTING.		1,800.00	1,100.00
			5,270.00	2,170.00
GRAND TOTAL			21,095.96	6,680.88

Report Ref No. CC6/CTI22012171/Upa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,300.00
---	--	--	----------

Report Ref No. CC6/CTI22012171/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 7971X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

