

09/11/23 Wsf
ASS. REC. BY: Rone

REF: C66/CT122012172/Rpa3


9113

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMF 4SSK
at Workshop m/s ARC
of TOH HUMAN AD ENG
Insured: CTI
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 84K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF 4SSK Yr Regn: 2018 / 6C7
Type: Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: TOYOTA SIENNA STANDARD A c.c. 1496
Colour: Brown A/C: Insured / Std / NI / NA
Sp. Reading: 50567 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: MHFZ28H3200059246

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: NI / SR / SR / SR / Rim or _____

Tyre Size: F: 185/60R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or ROADX

Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 01/12/22 D.O.I. 24/12/22

Survey held at ARC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - SSK

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

TOTAL

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2212-653-TG

DATE : 1-Dec-2022

POLICY NO. :

VEHICLE REG. NO. : **SMF455K**

VEHICLE MAKE : TOYOTA / SIENTA STANDARD (2018)

MHFZ28H3200059246

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de</i>	1	\$ 500.00	\$ 500.00
2	Rear Bumper Extension (Center) <i>de</i>	1	\$ 256.00	\$ 256.00
3	Rear Bumper Side RH <i>de</i>	1	\$ 190.00	\$ 190.00
4	Rear Bumper Side LH <i>sw</i>	1	\$ 190.00	\$ 190.00
5	Rear Bumper Side Retainer RH <i>X</i>	1	\$ 100.00	\$ 100.00
6	Rear Bumper Side Retainer LH <i>X</i>	1	\$ 100.00	\$ 100.00
7	Rear Bumper Clips <i>m</i>	10	\$ 5.50	\$ 55.00
8	Rear Tailgate <i>bt</i>	1	\$ 1,330.00	\$ 1,330.00
9	Rear Tailgate Weatherstrip <i>m</i>	1	\$ 453.00	\$ 453.00
10	Rear Tailgate Lock <i>?</i>	1	\$ 560.00	\$ 560.00
11	Rear Tailgate Emblem <i>m</i>	1	\$ 80.00	\$ 80.00
12	Rear Windscreen Moulding <i>m</i>	2	\$ 90.00	\$ 180.00
13	Rear End Panel <i>bt</i>	1	\$ 810.00	\$ 810.00
14	Rear End Panel Outer <i>X</i>	1	\$ 550.00	\$ 550.00
15	Rear End Panel Top Garnish <i>?</i>	1	\$ 220.00	\$ 220.00
Total Spare Parts				\$ 5,574.00
SPECIAL NETT				
16	Sealant <i>m</i>	1	\$ 60.00	\$ 60.00 <i>40</i>
17	Reverse sensor <i>m</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 260.00



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2212-653-TG
DATE : 1-Dec-2022
POLICY NO. :
VEHICLE REG. NO. : **SMF455K**
VEHICLE MAKE : TOYOTA / SIENTA STANDARD (2018)
MHFZ28H3200059246

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	LABOUR			
18	Spray painting (Rear Bumper, Rear Bumper Side (LH/RH), Rear Tailgate, Rear End Panel)	1	\$ 1,000.00	\$ 1,000.00
19	Repair, Refit, Remove and Replace Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
20	Transfer tailgate fitting and window mechanism to new tailgate	1	\$ 80.00	\$ 80.00
21	Remove and refit rear windscreen	1	\$ 120.00	\$ 120.00
22	Remove and Refit Rear Bumper Sensor	1	\$ 100.00	\$ 100.00
23	Check and Rectify Electric Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 2,350.00
Amount Before Excess				\$ 8,184.00
Add GST @ 7%				572.88
Total Amount Payable				\$ 8,756.88

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Razali
Up 90010068
6 days
4/5
21/12/22 @ 1240
Resurvey after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 911J

Vehicle No.: SMF455K

Vehicle to be Exported: No

Intended Deregistration Date: 22 Dec 2022

Vehicle Make: TOYOTA

Vehicle Model: SIENTA STANDARD (AUTO)

Primary Colour: Brown

Manufacturing Year: 2018

Engine No.: 2NRX392828

Chassis No.: MHFZ28H3200059246

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$17,705.00

Original Registration Date: 25 Oct 2018

First Registration Date: 25 Oct 2018

Transfer Count: 0

Actual ARF Paid: \$17,705.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Oct 2028

PARF Rebate Amount: \$13,278.00

COE Expiry Date: 24 Oct 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$25,556.00

COE Rebate Amount: \$14,921.00

Total Rebate Amount: \$28,199.00

The information contained herein is correct as at 22 Dec 2022

OK

Toyota Sienta 1.5A Standard

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$86,500****Depreciation** ⓘ

\$12,990 /yr

[View models with similar depre](#)**Reg Date**

14-Dec-2018

(5yrs 11mths 21days COE left)

Mileage

65,000 km (16.2k /yr)

Manufactured ⓘ

2018

Road Tax ⓘ

\$682 /yr

Transmission

Auto

Dereg Value ⓘ

\$27,344 as of today (change)

OMV ⓘ

\$17,664

COE ⓘ

\$23,568

ARF ⓘ

\$17,664

Engine Cap

1,496 cc

Power

79.0 kW (105 bhp)

Curb Weight ⓘ

1,325 kg

No. of Owners ⓘ

1

Type of Vehicle

MPV