

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : SPF ACCIDENT CLAIMS SECTION

AUTOMOTIVE ENGINEERING & MANAGEMENT

POLICE LOGISTICS DEPARTMENT 1 MOUNT

BLK 8 OLD POLICE ACADEMY S 298333

Estimate No: EST1508970

Date: 26 Nov 2022

Policy No: PNPV2022-00002483

Veh Reg No: SJP1681A

Make/Model: MAZDA MAZDA3 4DR
1.5 AT M-HYBRID
CLASSIC

ATTN: Motor Claim Department \ SPF

Your Ref No: TP 1122-7122

Claim Type: Third Party

Accident Date: 26/11/2022

TP Veh Reg No: QX 998 T

Chassis No: JM6BP2SAAM1108739

Engine No: P520757658

Reg. Date: 27/08/2021

Estimate Repair Cost to Vehicle No :SJP1681A

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER	998.0000	1 PC	998.00	
2 REAR BUMPER SIDE HOLDER - LH/RH	34.0000	2 PC	68.00	
3 REAR BUMPER CLIPS	5.0000	10 PC	50.00	
4 REAR BUMPER REINFORCEMENT	542.0000	1 PC	542.00	
5 REAR BUMPER TOW COVER - LH/RH	37.0000	2 PC	74.00	
6 REAR BUMPER REFLECTORS - LH/RH	36.0000	2 PC	72.00	
7 REAR BUMPER NUMBER PLATE LAMP - LH/RH	115.0000	2 PC	230.00	
8 REAR TAILLAMP - LH/RH	539.0000	2 PC	1,078.00	
9 REAR BOOT	896.0000	1 PC	896.00	
10 REAR BOOT HINGES - LH/RH	176.0000	2 PC	352.00	
11 REAR BOOT MAZDA LOGO	180.0000	1 PC	180.00	
12 REAR BOOT 'MAZDA 3' WORDINGS	35.0000	1 PC	35.00	
13 REAR BOOT 'M HYBRID' LOGO	0.0000	1 PC	0.0000	
14 REAR BOOT 'SKYACTIVE G' LOGO	43.0000	1 PC	43.00	
15 REAR BOOT RUBBER	154.0000	1 PC	154.00	
16 REAR BOOT LAMP - LH/RH	490.0000	2 PC	980.00	
17 REAR BOOT TOP LOCK	161.0000	1 PC	161.00	
18 REAR BOOT INSULATOR CLIPS	5.0000	7 PC	35.00	
19 REAR BUMPER SENSOR	190.0000	6 PC	1,140.00	
20 REAR BUMPER SENSOR WIRE	475.0000	1 PC	475.00	
21 REAR FENDER - LH	1,644.000	1 PC	1,644.00	
22 REAR FENDER COWLING - LH	173.0000	1 PC	173.00	
23 REAR FENDER COWLING CLIPS - LH	5.0000	10 PC	50.00	
24 REAR FENDER MUD FLAP - LH	84.0000	1 PC	84.00	
25 REAR GLASS MOULDING	50.0000	1 PC	50.00	
26 REAR EXHAUST CHROME - LH	399.0000	1 PC	399.00	
27 REAR END PANEL	692.0000	1 PC	692.00	
28 REAR END PANEL TOP GARNISH	70.0000	1 PC	70.00	
29 REAR FLOOR PANEL	1,244.000	1 PC	1,244.00	
30 REAR FLOOR PANEL TOP COVER	659.0000	1 PC	659.00	
31 REAR REVERSE CAMERA	1,017.000	1 PC	1,017.00	
			13,645.00	
		Less 20%	2,729.00	10,916.00
Special Net				
32 SEALANT	20.0000	2 PC	40.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : SPF ACCIDENT CLAIMS SECTION

AUTOMOTIVE ENGINEERING & MANAGEMENT
POLICE LOGISTICS DEPARTMENT 1 MOUNT
BLK 8 OLD POLICE ACADEMY S 298333

ATTN: Motor Claim Department \ SPF

Estimate No: **EST1508970**

Date: 26 Nov 2022

Policy No: PNPV2022-00002483

Veh Reg No: **SJP1681A**

Make/Model: MAZDA MAZDA3 4DR
1.5 AT M-HYBRID
CLASSIC

Chassis No: JM6BP2SAAM1108739

Engine No: P520757658

Reg. Date: 27/08/2021

Your Ref No: TP 1122-7122

Claim Type: Third Party

Accident Date: 26/11/2022


TP Veh Reg No: QX 998 T

Estimate Repair Cost to Vehicle No :SJP1681A

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
33 SPONGE TAPE	20.0000	1 PC	20.00	
34 REAR NUMBER PLATE WITH CASING	45.0000	1 PC	45.00	
35 FLOOR PANEL SEALANT	250.0000	1 PC	250.00	
			355.00	355.00
Labour				
36 TO REPLACE REAR END PANEL, AND SPARE TYRE FLOOR PANEL INCLUDING AFFECTED ATTACHEMENTS AND FITTING, CUT/WELD AND REALIGN	1,400.000	1 JOB	1,400.00	
37 TO RESPRAY PAINT ON ACCIDENT PORTIONS (INCLUDING REAR DOOR LH)	1,600.000	1 JOB	1,600.00	
38 TO CHECK WIRING	40.0000	1 JOB	40.00	
39 TO TUFF-KOTE	120.0000	1 JOB	120.00	
40 TO REMOVE, REFIT END PANEL GARNISH, CARPET, CUSHION & RELATED PARTS TO FACILITATE REPAIR	150.0000	1 JOB	150.00	
41 TO REMOVE, REFIT FUEL TANK TO FACILITATE REPLACEMENT OF FENDER	120.0000	1 JOB	120.00	
42 TO REMOVE, REPLACE REAR BUMPER SENSOR	120.0000	1 JOB	120.00	
43 TO REMOVE, REFIX REAR EXHAUST LH	150.0000	1 JOB	150.00	
44 TO REMOVE, REFIT REAR GLASS TO FACILITATE REPLACEMENT OF REAR FENDER	150.0000	1 JOB	150.00	
			3,850.00	3,850.00
			Total	S\$ 15,121.00
			Add GST @ 7%	1,058.47
			Total Amount Payable	<u>S\$ 16,179.47</u>

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND ONE HUNDRED SEVENTY NINE AND CENTS FORTY SEVEN ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE