

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 64276
Date Estimated : 06/12/2022
Prepared By : Inthiran A/L Thurasamy

Page No. :

- ESTIMATE REPAIR FOR -

Wee Gui Jun
38 Springside Green

Singapore 786903

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX803G	WBA70DY0X08C45657	16/03/2022	318i Sedan	12118

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# REAR BUMPER MOUNTING (MSP) <i>cm</i>	147.50	1.00	0.00	147.50
# REAR DIFFUSER <i>cm</i>	72.35	1.00	0.00	72.35

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	219.85
Total Labour & Parts (before GST) :	219.85

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Lou



GST REG. NO : M2 - 0020081 - X

ESTIMATE

6 Dec 2022

Estimate No. : b1 64276
Date Estimated : 06/12/2022
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Wee Gui Jun
38 Springside Green

Singapore 786903

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX803G	WBA70DY0X08C45657	16/03/2022	318i Sedan	12118

DESCRIPTION

To replace rear bumper and attachments.

To painting rear bumper.

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

Sundries.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Any complementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE

850 1,275.00

986 1,038.00

168 177.00

168 177.00

80.00

Total Labour 1: 2,747.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
Set of mount <i>See X m</i>	1	70.05	70.05
REAR BUMPER TRIM PANEL BOTTOM (MSP) <i>See de</i>	1	232.75	232.75
REAR BUMPER TRIM PANEL (MSP/MPA PDC) <i>See de</i>	1	1,600.45	1,600.45

Total Parts : 1,903.25

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 27/12/22 01:45 Excess S\$

Surveyor's Name RAN Sign

Surveyor's Tel 900 100 68 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 3 days

Labour 1 : 2,747.00

Parts : 1,903.25

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 325.52

Grand Total : 4,975.77



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **