

(08/11/23) Wof

ASS. REC. BY: Amu

REF:

CS/CT122012183/RP3

199F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLX 8036at Workshop n/s PERFORMANCEof 303, BLKAMARA RDInsured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 208K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLX 8036 Yr Regn: 2022 MAR

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 318I MSPTADPTLEHLC 1998Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 17589 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: USA 70046X0845657

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 225/45R18R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HANKOOK

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/11/22 D.O.I. 27/12/22Survey held at PERFORMANCEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LMT - 20K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS, SI

Photos

Others

TOTAL

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

LOU



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

6 Dec 2022

Estimate No. : b1 64276
Date Estimated : 06/12/2022
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Wee Gui Jun
38 Springside Green

Singapore 786903

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX803G	WBA70DY0X08C45657	16/03/2022	318i Sedan	12118

DESCRIPTION

To replace rear bumper and attachments.

To painting rear bumper.

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

Sundries.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Any supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE

850 1,275.00

986 1,088.00

168 177.00

168 177.00

80.00

Total Labour 1: 2,747.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
Set of mount	1	70.05	70.05
REAR BUMPER TRIM PANEL BOTTOM (MSP)	1	232.75	232.75
REAR BUMPER TRIM PANEL (MSP/MPA PDC)	1	1,600.45	1,600.45

Total Parts : 1,903.25

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 27/12/22 01:45 Excess S\$

Surveyor's Name RSM Sign

Surveyor's Tel 900 10068 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 3 days



Labour 1	:	2,747.00
Parts	:	1,903.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	325.52
Grand Total	:	4,975.77

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	179F

Vehicle No:	SLX803G
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2022
Vehicle Make:	B.M.W.
Vehicle Model:	318i MSPT ADPT LED HL
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	F4644081B48B20A
Chassis No.:	WBA70DY0X08C45657
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$43,959.00
Original Registration Date:	16 Mar 2022
First Registration Date:	16 Mar 2022
Transfer Count:	0
Actual ARF Paid:	\$53,543.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2032
PARF Rebate Amount:	\$40,157.00

COE Expiry Date:	15 Mar 2032
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$94,889.00
COE Rebate Amount:	\$87,391.00
Total Rebate Amount:	\$127,548.00

The information contained herein is correct as at 28 Dec. 2022

OK

BMW 3 Series 318i M-Sport

Overview

Financial

Accessories

Similar

Research

Photos

Map



CAR CHOICE
SINGAPORE

The Best Buying Experience



Price	\$208,800		
Depreciation	\$19,700 /yr View models with similar depre	Reg Date	31-Mar-2022 (9yrs 3mths 2days COE left)
Mileage	598 km	Manufactured	2021
Road Tax	\$1,210 /yr	Transmission	Auto
Dereg Value	\$112,911 as of today (change)	OMV	\$43,427
COE	\$98,890	ARF	\$52,798
Engine Cap	1,998 cc	Power	115.0 kW (154 bhp)
Curb Weight	1,490 kg	No. of Owners	1