



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOH CYNTHIA			Ref: CS/ASM22012186/Tqp3e2 Date: 28/03/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 4608X	Veh. Inspected	SNC 2927G
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04FXE	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	05/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA WISH	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	ZGE200024557	Colour	WHITE
	Odometer	200897 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	6 mm
	L/H Front Tyre	205/55 R16	MICHELIN	6 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/12/2022	Inspection Date	07/12/2022
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	