

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TPA x A.
Xiao Chen,

ESTIMATE

Vehicle No : SNC2927G

Make/Model : TOYOTA WISH

Chassis No: ZGE200024557

Accident date : 03.12.2022

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Front bumper <i>Distorted</i>	1	\$ 530.00 ✓
2	Front bumper side holder @ \$188.60 <i>RH Dnd</i>	2	\$ 377.20 <i>58.</i>
3	Front bumper reinforcement <i>Dented.</i>	1	\$ 318.90 ✓
4	Front bumper sponge <i>crushed</i>	1	\$ 189.70 ✓
5	Front bumper bracket @ \$189.30 <i>new</i>	2	\$ 378.60 <i>x.</i>
6	Front bumper fog lamp cover @ \$304.80 <i>RH Dented.</i>	2	\$ 609.60 <i>125.</i>
7	Front bumper lower side grille @ \$216.10 <i>RH Dented</i>	2	\$ 432.20 <i>85.</i>
8	Front grille <i>crushed.</i>	1	\$ 408.90 <i>327.</i>
9	Front headlamp @ \$1,883.60 <i>LH crushed, RH smashed.</i>	2	\$ 3,767.20 <i>2580.</i>
10	Front headlamp lower bracket @ \$189.70 <i>new</i>	2	\$ 379.40 <i>x.</i>
11	Front support panel <i>crushed.</i>	1	\$ 1,069.50 <i>874.</i>
12	Front support panel top cover <i>Dented</i>	1	\$ 318.90 ✓
13	Front bonnet <i>Dented.</i>	1	\$ 640.10 ✓
14	Front bonnet hinge @ \$133.50 <i>?</i>	2	\$ 267.00 <i>x</i>
15	Front bonnet insulation <i>new</i>	1	\$ 409.00 <i>x</i>
16	Front bonnet rubber	1	\$ 208.00 <i>x.</i>
17	Front bonnet emblem <i>new</i>	1	\$ 133.20 <i>65</i>
18	Front bonnet lock <i>new</i>	1	\$ 200.40 <i>x</i>
19	Front bonnet lock bracket <i>new</i>	1	\$ 191.00 ✓
20	Front RH fender <i>Repair</i>	1	\$ 933.60 <i>x.</i>
21	Front fender inner shield @ \$181.70 <i>RH torn</i>	2	\$ 363.40 <i>181.70.</i>
22	Wiper tank <i>Dented</i>	1	\$ 220.00 <i>145.</i>
23	Aircond condenser <i>Dented.</i>	1	\$ 1,418.00 ✓
24	Radiator <i>Dented.</i>	1	\$ 2,205.50 <i>1493</i>
25	Front engine lower cover <i>torn</i>	1	\$ 380.00 <i>245</i>
26	Rear condenser side garnish @ \$75.00 <i>RH Dented</i>	2	\$ 150.00 <i>35.</i>
			\$ 16,499.30
Less 25% Disc			\$ 4,124.83
Total			\$ 12,374.48

9840.30

7380.22

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SNC2927G

Make/Model : TOYOTA WISH

Chassis No: ZGE200024557

Accident date : 03.12.2022

No	DESCRIPTION	Qty	Amount (\$S)
Special Nett Items			
1	Front bumper clips (1 set) <i>3 New</i>	1	\$ 70.00 <i>30</i>
2	Front RH fender inner shield clips (1 set) <i>3 New</i>	1	\$ 60.00 <i>30</i>
3	Front support panel clips (1 set) <i>New</i>	1	\$ 95.20 <i>20</i>
4	Front number plate <i>3 New</i>	1	\$ 50.00 <i>x</i>
5	Front number plate holder <i>3 New</i>	1	\$ 50.00 <i>x</i>
<i>6 Coolant New 600 130</i>		Total	\$ 325.20
Labour Cost			
1	To check wiring		\$ 80.00 <i>30</i>
2	Remove & reinstall aircond fill in gas		\$ 150.00 <i>120</i>
3	Remove ,replace & repair consistent to the accident		\$ 1,500.00 <i>800</i>
4	Respray painting		\$ 1,500.00 <i>800</i>
5	Tuff kote		\$ 100.00 <i>60</i>
<i>6 Remove and reinstall radiator and to top up coolant</i>		Total	\$ 3,330.00 <i>120 60</i>
<i>1870</i>		Grand Total	\$ 16,029.68

total 9380.22
1/s. 7.5k.
08 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7.5k