

(08/11/83) Wef

ASS. REC. BY: John

REF:

CS/CH/22012188/Rvy3

3360

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ T/P / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MVTo inspect Vehicle No: SLF 879Kat Workshop n/s Movaof FransuoonhInsured: Ch

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 77K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 37KVeh No: SLF 879K Yr Regn: 2016 188Type ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: TOYOTA HARRIER 2.0A 1986Colour: BLACK A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 67891 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: 254600074282Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 235/55R18

R: _____

BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

KAPSEN

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 01/12/22D.O.I. 06/12/22Survey held at Mova (FY)Des. of Damages ☒ Front / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Others (\$ _____)

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____



Main Office : No. 22, Jalan Kilang, Singapore 169419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 169722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System,

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22011610	Date of Loss:	01/12/2022
Vehicle Reg. No.:	SLF8779K	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TEO CHIN LIAN		
Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	14/09/2016
Vehicle Colour:	BLACK	Chassis No:	ZSU600074282
Engine No:	3ZRB746739		
Odometer:	67891 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS	Amount
Parts	7,404.30
Miscellaneous Items	0.00
Labour	2,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,484.30
+ GST 7.00% (\$\$)	663.90
Nett Amount (\$\$)	10,148.20

This claim is handled by: ONG

PAIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2022)
 s: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
 ur: Repairer's (Price-denominated Standard List)
 Code: (Unsubmitted, no print-code for SLF8779K)
 ity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 er Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*FRONT BONNET MOULDING <i>ca</i>	0.00	0.00	*185.00 F
1		*FRONT BONNET LOCK STAY PANEL <i>bt</i>	0.00	0.00	*138.00 F
1		*FRONT GRILLE <i>ca</i>	0.00	0.00	*320.00 F
1		*FRONT GRILLE CLIPS <i>ca</i>	0	0.00	*30.00 FS
1		*FRONT BUMPER <i>de</i>	0.00	0.00	*380.00 F
1		*FRONT BUMPER LOWER GRILLE <i>ca</i>	0.00	0.00	*155.00 F
1		*FRONT BUMPER CLIPS <i>ca</i>	0	0.00	*40.00 FS
1		*FRONT BUMPER REINFROCEMENT <i>bt</i>	0.00	0.00	*300.00 F
2		*FRONT BUMPER INNER SPONGE UPPER LH/RH <i>ca</i>	0.00	0.00	*144.00 F
1		*FRONT BUMPER INNER SPONGE LOWER <i>de</i>	0.00	0.00	*88.00 F
1		*FRONT BUMPER TOWING COVER RH <i>ca</i>	0.00	0.00	*30.00 F
1		*FRONT BUMPER SIDE RETAINER BRACKET LH <i>ca</i>	0.00	0.00	*75.00 F
1		*FRONT BUMPER SIDE RETAINER BRACKET RH <i>ca</i>	0.00	0.00	*75.00 F
1		*FRONT BUMPER LOWER LIP <i>de</i>	0.00	0.00	*210.00 F
1		*FRONT SUPPORT PANEL TOP COVER CLIPS <i>X</i>	0	0.00	*40.00 FS
1		*FRONT AIR COND CONDENSOR <i>?</i>	0.00	0.00	*880.00 F
1		*FRONT HEADLAMP LH <i>ca</i>	0.00	0.00	*1,480.00 F
1		*FRONT HEADLAMP RH <i>ca</i>	0.00	0.00	*1,480.00 F
1		*FRONT UNDER COVER <i>ca</i>	0.00	0.00	*93.00 F
1		*FRONT FENDER LH <i>bt</i>	0.00	0.00	*480.00 F
2		*FRONT FENDER INNER LINER CLIPS LH/RH <i>ca</i>	0	0.00	*80.00 FS
1		*FRONT NUMBER PLATE <i>ca</i>	0	0.00	*30.00 FS
1		*FRONT NUMBER PLATE HOLDER <i>ca</i>	0	0.00	*20.00 FS
1		*FRONT BONNET (REPAIR)	0.00	0.00	-
1		*FRONT SUPPORT PANEL (REPAIR)	0.00	0.00	-
1		*FRONT RH FENDER (REPAIR)	0.00	0.00	-
1		*FRONT LH DOOR (REPAIR)	0.00	0.00	-
Sub Total (\$\$)					6,753.00
+ Margin on L,N Items 10.00% (\$\$)					651.30
Total Parts (\$\$)					7,404.30

Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, REFIT & REPLACE FRONT AIR COND CONDENSOR, AIR COND PIPE & ETC.	New	100.00 X
2	TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER LH/RH, FRONT DOOR LH & ETC. BACK TO ORIGINAL CONDITIONS	New	500 600.00
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH, FRONT DOOR LH & ETC.	New	1100 1000 1,200.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	30 80.00
5	TO REFILL AIR COND GAS & VACUUM	New	80 100.00
Gross Labour Cost (\$)			2,080.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

6 days

P/P

06/12/22 @ 1640

EXCESS: 500

Reveal

Resurvey ~~after~~
before paint

email: rasul@lkkauto.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 336D

Vehicle No.: SLF8779K

Vehicle to be Exported: No

Intended Deregistration Date: 07 Dec 2022

Vehicle Make: TOYOTA

Vehicle Model: HARRIER ELEGANCE 2.0A

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: 3ZRB746739

Chassis No.: ZSU600074282

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$28,882.00

Original Registration Date: 14 Sep 2016

First Registration Date: 14 Sep 2016

Transfer Count: 0

Actual ARF Paid: \$27,435.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Sep 2026

PARF Rebate Amount: \$17,832.00

COE Expiry Date: 13 Sep 2026

COE Category: E - Open Category

COE Period (Years): 10

QP Paid: \$56,889.00

COE Rebate Amount: \$21,428.00

Total Rebate Amount: \$39,260.00

The information contained herein is correct as at 07 Dec 2022

OK

Toyota Harrier 2.0A Elegance

Overview

Financial

Accessories

Similar

Research

Photos

Map



Car Search

We Represent You

Price **\$77,800**

Depreciation **\$17,090 /yr**
View models with similar depre

Reg Date 09-Sep-2016
(3yrs 9mths 1day COE left)

Mileage 55,900 km (8.9k /yr)

Manufactured 2016

Road Tax \$1,196 /yr

Transmission Auto

Dereg Value \$38,400 as of today (change)

OMV \$28,749

COE \$55,100

ARF \$27,249

Engine Cap 1,986 cc

Power 111.0 kW (148 bhp)

Curb Weight 1,610 kg

No. of Owners 3