

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22012190/KQY3Q2**Date:** 07/06/2023**REFERENCE**

Insured/Claimant: CHOW YONG CHIENG, JEREMY
Date of Loss: 30/11/2022

Policy No: SP2001895805
Nature of Claim: OD

Claim No: 202222008572

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ257U**
Make & Model: NISSAN X-TRAIL, 2.0 (A)
Reg. Date: 27/06/2017 (Man. Year: 2017)
Colour: Grey
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$79,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: MR20999725B
Chassis No: JN1JANT32Z0003296
Odometer: 92709 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,723.40	3,706.45	4,016.95	52.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,120.00	1,440.00	56.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,283.40	4,826.45	5,456.95	53.07
Approved Total (Overridden) (\$\$)		3,850.00		
- Excess (\$\$)	600.00	600.00	0.00	0.00
Nett Amount (\$\$)	9,683.40	3,250.00	6,433.40	66.44

INSPECTION

Date of Assignment: 06/12/2022

Date Inspected: 06/12/2022 Inspected At:

Sin Heng Long Motor Work (Ang Mo Kio)
Blk 5032 Ang Mo Kio Industrial Park 2, #01-305
Singapore 569535

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts:	M1-MPV	NISSAN X-TRAIL 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ257U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOORC		-	-
2	1		*LH FRONT DOOR (WCP)	Bent	955.00 F	*650.00 F
3	1		*LH FRONT DOOR LOWER HINGE (WCP)	Repair	135.00 F	*- F
4	1		*LH FRONT DOOR UPPER HINGE (WCP)	Repair	135.00 F	*- F
5	1		*LH FRONT DOOR CABLE HOUSING (WCP)	Serviceable	89.00 F	*- F
6	1		*LH FRONT FENDER (WCP)	Bent	420.00 F	*310.00 F
7	1		*LH FRONT FENDER SHIELD (WCP)	Serviceable	158.50 F	*- F
8	1		*LH FRONT FENDER PROTECTOR (WCP)	Dented	156.00 F	*156.00 F
9	1		*LH SIDESKIRT (WCP)	Serviceable	476.00 F	*- F
10	1		*LH DOOR PROTECTOR (WCP)	Dented	156.00 F	*156.00 F
11	1		*NISSAN SPORT RIM (WCP)	Dented	1,380.00 F	*1,000.00 F
12	1		*LH LOWER ARM (WCP)	Distorted	258.00 F	*258.00 F
13	1		*LH LINKAGE (WCP)	Distorted	58.00 F	*58.00 F
14	1		*LH KNUCKLE (WCP)	Bent	455.00 F	*420.00 F
15	1		*LH WHEEL BEARING (WCP)	Necessary	268.00 F	*120.00 F
16	1		*STABLIZER BAR BUSH (WCP)	Not Necessary	30.00 F	*- F
17	1		*FRONT CROSS MEMBER (WCP)	Serviceable	895.00 F	*- F
18	1		*TIE ROD END (WCP)	Distorted	95.00 F	*95.00 F
19	1		*NUTS AND CLIPS	Not Necessary	80.00 FS	*- FS
20	1		*TYRE	Not Necessary	250.00 FS	*- FS
21	5		*RIM NUT	Not Necessary	50.00 FS	*- FS
						F=Franchise part. S=SpcNett.
					Sub Total (\$\$)	6,499.50 3,223.00
					+ Margin on L,N Items 20.00/15.00% (\$\$)	1,223.90 483.45
					Total Parts (\$\$)	7,723.40 3,706.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND WELDING ON ACCIDENT AREAS	New	800.00	400.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	900.00	400.00
3	ANTI RUST	New	80.00	0.00
4	LABOR TO RENEW SENSOR WIRING	New	120.00	0.00
5	LABOR TO APPLY DOOR SEALER	New	40.00	0.00
6	LABOR TO REMOVE & REFIT UNDERCARRIAGE	New	400.00	200.00
7	LABOR TO TRANSFER DOOR WINDOW & PARTS	New	120.00	60.00
8	4 WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (S\$)			2,560.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >