

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 07 Dec 2022

Preliminary Advice

Vehicle No	: SLQ257U	Accident Date	: 30/11/2022
Make	: NISSAN X-TRAIL	Policy No.	: SP2001895805
Assignment Date	: 06/12/2022	Excess	: S\$600.00
Date of Inspection	: 06/12/2022	Est. Duration of Repair	: 4
Inspection At	: SIN HENG LONG MOTOR WORK (ANG MO KIO) BLK 5032 ANG MO KIO INDUSTRIAL PARK 2, #01-305 SINGAPORE 569535		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,283.40
Revised Amount	:S\$	4,600.40
Check Items (Estimated)	:S\$	3,596.20
Total	:S\$	8,196.60

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	42,178.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,822.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
REPAIRER REFUSE TO ACCEPT THE COST PLUS 10%, THEY REQUEST COST PLUS 15% AS THEIR NOT AN AUTHORISE WORKSHOP.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.