

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	M6928
Policy No:	SP2001491346	Date of Loss:	24/11/2022
Vehicle Reg. No.:	SMK4244B A	Driveable?	YES
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GEORDON ONG TA YONG		
Make/Model:	MERCEDES-BENZ GLA200 1.6 URBAN (R18 LED) (A) 180	Vehicle Reg. Date:	10/04/2019
Vehicle Colour:	Metallic Pearl White	Gen Condition:	Fair
Engine No:	27091031837393	Chassis No:	WDC1569422J601464
Odometer:	69837 KM		
Paint Type:	Metallic 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	AUTO INSURE PTE LTD (HQ) (WOODLANDS)		

COST OF CLAIMS

	Amount
Parts	8,173.00
Miscellaneous Items	0.00
Labour	1,500.00
Paintwork Labour	800.00
Towing	0.00
Calculated Gross Total (S\$)	10,473.00
- Excess (S\$)	800.00
(S\$)	9,673.00
+ GST 7.00% (S\$)	677.11
Nett Amount (S\$)	10,350.11

This claim is handled by: **MARVYN CHUA HONG LENG**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2022)

Parts: M1-SUV MERCEDES-BENZ GLA200 1.6 URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Auto Insure Pte Ltd (HQ)/SMK4244B/08/12/2022 10:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR RH — BUC	0.00	0.00	*1,635.00 F
2	1		*REAR DOOR HINGE LOWER RH }?	0.00	0.00	*200.00 F
3	1		*REAR DOOR HINGE UPPER RH }	0.00	0.00	*200.00 F
4	1		*REAR FENDER RH XR	0.00	0.00	*2,185.00 F
5	1		*REAR WHEEL ARCH GARNISH RH CUT	0.00	0.00	*200.00 F
6	1		*REAR BUMPER X R	0.00	0.00	*1,060.00 F
7	1		*REAR BUMPER SIDE RETAINER RH ?	0.00	0.00	*30.00 F
8	1		*REAR WHEEL RIM RH — CUT	0.00	0.00	*830.00 F
9	1		*REAR LOWER CONTROL ARM RH ?	0.00	0.00	*75.00 F
10	1		*REAR DOOR HANDLE RH XR	0.00	0.00	*370.00 F
11	1		*REAR WHEEL HUB RH	0.00	0.00	*330.00 F
12	1		*REAR WHEEL BEARING RH }?	0.00	0.00	-
13	1		*REAR CAMBER STRUT RH }	0.00	0.00	*115.00 F
14	1		*REAR UPPER CONTROL ARM RH }	0.00	0.00	*200.00 F

F=Franchise part.

Sub Total (S\$)	7,430.00
+ Margin on L,N Items 10.00% (S\$)	743.00
Total Parts (S\$)	8,173.00

Auto Insure Pte Ltd (HQ)/SMK4244B/08/12/2022 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR FOR SPRAY PAINTING	New	800.00
<u>Labour Items</u>			
2	LABOUR FOR PANEL BEATING	New	1,000.00
3	LABOUR TO REMOVE & REFIT REAR DOOR MECHANISM RH	New	200.00
4	LABOUR TO REMOVE AND REFIT REAR SUSPENSION RH	New	200.00
5	LABOUR FOR ALIGNMENT & BALANCING	New	100.00
Gross Labour Cost (\$\$)			2,300.00

Auto Insure Pte Ltd (HQ)/SMK4244B/08/12/2022 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P/P or L/S ?

P/P 5 days